


BEAVIS & COCHRANE



HYDRAULIC SERVICES CONSULTANTS A.H.S.C.A.

Suite 2, 115 Scarborough Street, Southport Qld
P.O. Box 1711, Southport Qld 4215

Proprietor: Topcare Pty Ltd
A.C.N. 054 335 634
A.B.N. 60 054 335 634
B.S.A. Lic. No: 744 074

Ph: [REDACTED]
Fax: [REDACTED]

DRAFT REPORT

GKB:LG:6826

31st January 2011

Mirvac Development Group
PO Box 5121
West End Q Brisbane 4101

Att: Mr [REDACTED]

RE: TENNYSON BUILDING 34 AND 41

Dear [REDACTED]

At your request our office has been to site with the purpose of identifying why stormwater may have entered the basement area's through the stormwater system before flood waters reached a level at which time they would enter the basement via the ramp and stairs.

Our office was not on site during the flood event and therefore did not witness water infiltration first hand.

GENERAL DESCRIPTION OF SYSTEM

The majority of the building stormwater discharges to a rain water collection tank in the visitors carpark. The 450mm tank overflow runs through the carpark then enters at low level of basement 2 before running 'inground' under the basement slab. External of the basement wall this line connects to a civil manhole, with a solid lid at locations along the length of drain downstream of the raintank are connections to points located within basement 1.

PROBABLE CAUSE FOR STORMWATER ENTERING BASEMENTS PRIOR TO STAIRWELL THRESHOLD BEING BREACHED

Under what would be considered usual rain events you would not expect water to enter the basement via the stormwater system. We believe the reason for what occurred in the recent flood event was as follows.

There are a number of drain points within the basement, eg basement 1 ramp grate and safetray drains located under basement 1 that are directly connected to the stormwater discharge line. Therefore as the external water level rose once it reached about RL.4.700 (safetray drain) and RL.5.1 ramp drain outlet, water would flow into the basement as these are the lowest open points.

JM

6/10/11
741

Date:

Exhibit Number:

QFCI

In addition to these points once the system become flooded, that is a water level near or over the external surcharge gully, then the gravity pipe system under that RL would be under a constant static head. The system under this static head by reports developed leaks to fittings with rubber ring joints.

The joints exist to the 450 FRC stormwater bends inside the basement and the expansion joints on the 100mm drain receiving pump discharge and safetray drains. Check valves on the pump lines prevented water flowing back to the mini pump station sumps.

Refer the attached sketches H2 for further information.

Should you require any further information, please do not hesitate to contact the writer.

Yours faithfully

BEAVIS & COCHRANE



EXISTING GROUND LEVEL
MAX 1000 FILL.

ENERGEX EASEMENT.

225" SEWER THROUGH
WALL

IL 4.800.

IL 4.450.

SECTION A

SCALE: NTS

**Surcharge
Gully
RL 4-125**

**out-fall
To River**

FH
100

STW
450

01

CROSS under B-2 Slab
FOR CONTINUATION
REFER TO DWG H5003

**B2-RC 240
M1-RC 510 M.H
60-RC 400 R W-5**

300" STORMWATER
CAPPED AT BOUNDARY
FOR CONTINUATION
BY CIVIL CONTRACTOR.
IL: 1.800

IL 2.47
IL 3.54
IL 3.69

150" SLUICE VALVE

FH

FH

HT

IL 3.89

450

RW

IL 3.69

FOR CONTINUATION
REFER TO PDS
PLANS 4114900

225

**B1
gate
RL 5.100**

IL 4.800
THROUGH WALL

06

150" ORG WITH HT OVER


A


A

05

BUILDING 1

EXISTING 250" PE
SEWER MAIN.





A-A

73-73