On Behalf of the Body Corporate For

25th March 2011

Energex Limited Attention: Customer Service Team Leader GPO Box 1461 Brisbane QLD 4001

Dear Customer Service Team Leader,

RE: WATER INUNDATION RESPONSIBILITY

We write to you on behalf of the Body Corporate for located on the corner of Brisbane 4000.

We enclose a copy of the Engineers Report prepared by Sheehy & Partners Pty Ltd after water inundation occurred over the period 12th to 14th January 2011.

The report states that 'the source of the water inundation is believed to be at the incoming electricity mains to the Street Frontage. The water staining on the vermiculite encasing of the incoming building on the conduits and failed fire proofing of the entry location boxing soffit also confirm the likelihood of this location being the main source of water entry into the building.'

The Body Corporate strongly believes that Energex should assume responsibility for the water inundation based on the engineer's findings in the attached report.

We look forward to your response.

Yours faithfully,

Kate O'Rourke

Community Manager

For and on behalf of the Secretary of the Body Corporate

Please direct any correspondence to our Brisbane office.

Q:\bcm\35634\DOCS\Correspondence\2011\letter to energex re water inundation 240311.doc

STEWART SILVER king and burns COMMUNITY MANAGERS sskb@sskb.com.au www.sskb.com.au SSKB Body Corporate Management Pty Ltd ABN 59 100 137 862