From:

Dan Spiller

Sent:

To:

Subject: Attachments: Saturday, 15 January 2011 8:32 AM
'jbs2000 '; 'Bradley John'
Discussion Paper on Dam Full Supply Level Investigations Seqwater Gated Storages
Discussion Paper on Dam Full Supply Level Investigations Seqwater Gated

Storages.docx

Attachment 1

Discussion Paper on Dam Full Supply Level Investigations Sequater Gated Storages

Summary of comments

The attached paper summarises an analysis that changing the initial storage level of dams has on downstream flood impacts.

Wivenhoe/Somerset System

The analysis shows that for some minor floods similar to October 2010, reducing the starting volume of Wivenhoe Dam by 5% or 10% has minimal impacts on impacts downstream. The main benefit being that inundation times for downstream bridges will be reduced but only by around 15%. However peak water levels are not affected. There are minimal potential benefits to downstream bridge until dam levels are reduced down to about 50% of capacity.

These results are not unexpected as Wivenhoe has such a large flood storage. Adding say 100,000ML to the flood storage (equates to reducing the storage volume by 10%) does not appreciably increase this available flood storage.

It should also be noted that in many cases, Wivenhoe flood releases will be made following the peaks of inflows into the Brisbane River from the Lockyer and Bremer Catchments. Certainly during many events, Lockyer Creek could already have inundated most or all of the road crossings downstream of Wivenhoe Dam. In these instances, a small amount of additional flood storage in the dam provides minimal benefit.

Another option considered was pre-releasing Wivenhoe water in anticipation of a flood event. This is not considered a viable option for the following reasons:

- Regardless of forecast, there is never any certainty on the amount of rain that will fall
 within a dam catchment. For example, on 29 November 2010, the quantitative
 forecast from BOM for the Wivenhoe Catchment was 25 to 50 millimetres. Actual
 rainfall received was in the order of 10 millimetres. On a saturated catchment this
 could equate to a runoff discrepancy of hundreds of thousands of megalitres. A prerelease of anticipated flood water based on forecast could result in major
 embarrassment.
- Any significant pre-release of water would result in bridge inundation below Wivenhoe Dam.
- Any pre-release of water from Wivenhoe Dam will take at least 24 hours to reach the lower end of the Brisbane River system. Rains occurring in the catchments below the dam over this period could potentially worsen downstream flood impacts.

The Bureau of Meteorology has been contacted and they have confirmed the above forecast reliability assessment. They advised that, whilst weather prediction models are steadily improving, the forecast of rainfall amounts over catchment time/space scales is recognised as one of the most challenging/difficult tasks. Detailed rainfall forecasting is not deterministic - the uncertainties involved are often expressed in probablistic forecasts and whilst there is often the ability to forecast the potential for a significant rain event to occur in the southeast

Qld-northern NSW region, it is difficult (if not impossible) to predict the actual location of the heaviest rain, even with only a few hours notice.

The Queensland Director of Dam Safety (Mr Peter Allen) was contacted and he confirmed the assessment that minor reductions in the stored volume of Wivenhoe Dam would have minimal impacts on floods downstream and concurred with the risks involved in any pre release of significant volumes of water from dams prior to an event.

North Pine and Leslie Harrison Dams

Lowering the normal FSL for North Pine and Leslie Harrison Dams will have minimal impact on major floods and may not decrease releases depending on the size of even minor events. However lowering the level of North Pine Dam after a flood release to between 95% and 100% may reduce the frequency of operations in some rain events although the main benefit is in operational efficiency as it provides more time for response and may reduce making releases in a minor storm event.

Similarly reducing Leslie Harrison level to around 95% after or before an event could assist in reducing call out of staff and manning the storage for minor releases and even the timing of releases.

Normally both dams are returned to just under 100% after an event based on base inflows still occurring and possible further rain. Allowing the dams to reduce to around 95% improves the operational leeway. However this could best be provided by an operational arrangement where the WGM simply agrees Seqwater has the operational latitude to reduce both storages to between 95% and 100% after an event or when there is some inflow and Seqwater can decide the exact level based on ongoing inflows and possible predicted rainfall, but not going below 95%.

DAM FULL SUPPLY LEVEL (FSL) INVESTIGATIONS SEQWATER GATED STORAGES

INTRODUCTION

The following short paper examines the issues associated with temporary lowering the full supply levels of Seqwater's gated dams to improve short term flood mitigation benefits. The paper considers Wivenhoe Dam, Somerset Dam, North Pine Dam and Leslie Harrison Dam.

WIVENHOE DAM AND SOMERSET DAM

Wivenhoe Dam and Somerset dam control only 50% of the Brisbane River catchment (Bremer River and Lockyer Creek catchments are not controlled), therefore the Flood Mitigation benefits provided by the dam will depend on the rainfall distribution experienced during a flood event. This makes it difficult to quantify exactly the benefits of lowering the storage in anticipation of possible flood rains.

There are primarily two types of flood events that may occur in the Brisbane River Catchment. There are the smaller events that impact primarily on the rural bridges upstream of Moggill and the larger events that impact on urban areas in Brisbane. The threshold that separates these two events is a river flow of around 3500 cubic metres per second at Moggill. To understand the possible benefits of lowering the storage to reduce flooding impacts, it makes sense to discuss these two types of events separately.

Events Impacting on Bridges (Moggill Flow < 3500m³/s) – Limited Urban Impacts

In recent history, flood events of this nature occurred in April 1989, February 1999 and October 2010. The flow characteristics of events of this type are shown in the following table.

	Wivenhoe Dam					
Event	Starting Level		Volume Of Inflow	Volume Of Outflow	Peak Outflow	Peak Water Level
	m AHD	%	ML	ML	m3/s	m AHD
Early April 1989	67.06	>100	690,000	690,000	1,620	69.78
Late April 1989	67.00	100	870,000	820,000	1,490	71.45
February 1999	63.92	<100	1,220,000	900,600	1,800	70.45
October 2010	67.03	>100	640,000	640,000	1,300	69.65

The October 2010 event was examined to determine the benefits of lowering the storage level. This event commenced with the dam at FSL. The event was examined with the dam at 95% capacity, 90% capacity, 80% capacity, 50% capacity and empty at the commencement of the event. The results are shown in the following table. When reading the table it is important to understand that the bridges are impacted not just by outflows from Wivenhoe, but also by flows from the uncontrolled areas of the river catchment. Accordingly, the location of a bridge within the system will dictate the size of catchment area that will impact on the bridge. All inundation times shown in the table are approximations only, made for the purposes of this investigation.

Dam Percentage	Approximate	Approximate	Approximate	Peak Flow at
Full at Event	Duration of	Duration of	Duration of Burtons	Moggill
Commencement	Wivenhoe Radial	Savages Crossing	Bridge and Kholo	(m³/s)
	Gate Releases/	and Colleges	Bridge Inundation	
	Twin Bridges	Crossing Inundation	(hours)	
	Inundation	(hours)		
	(hours)			
100%	230	247	183	1848
95%	187	214	183	1848
90%	185	214	183	1841
80%	172	214	183	1786
50%	130	214	153	1722
0%	0	189	38	940
<u> </u>				

The table shows that the reduction in FSL won't have a large impact on Bridge inundation times. A reduction in the order or 36 hours or 15% of the total inundation time may be possible for the low level bridges only. The reductions are generally caused by the delay in release commencement associated with the lower starting FSL. However, the bridges can often already inundated at this time anyway due to flood inflows into the Brisbane River from the 50% of the catchment not controlled by Wivenhoe Dam. Lowering the FSL of the dam has no impact on such inundations as shown in the table.

For events smaller than those considered above, it should be noted that the Manual of Flood Mitigation allows a trigger level buffer of 27500 megalitres above FSL and this has the effect of protecting Twin Bridges and the lower level bridges from inundation as a result of minor events. Twin Bridges is essentially a low level causeway that is inundated following any radial gate release. This inundation could possibly be prevented by raising the bridge deck level. Regardless, the areas accessed using this bridge can also be accessed using the Fernvale Bridge. It is acknowledged however that the closing of Twin Bridges causes inconvenience to local residents, as it adds approximately another five kilometres to the journeys to and from their residences. Approximately 40 residences and several businesses (primarily turf farms) are impacted.

Events Impacting on Urban Areas (Moggill Flow > 3500m³/s) – All rural bridges inundated

Events of this nature have not been experienced since the construction of Wivenhoe Dam was completed in 1984, with the last event of this nature being experienced in 1974. The inflow volume into Wivenhoe Dam associated with the 1974 event has been estimated to be in the order of 1.5 million megalitres. However during the 1974 event, an additional 1.5 million megalitres of flood flow impacting of the urban areas of Brisbane originated from catchment areas that are not controlled by Wivenhoe Dam.

For events of this nature, it is unlikely that peak water levels in Brisbane would be significantly impacted by minor reductions in the level of Wivenhoe Dam. Certainly reductions in dam volume in the order of at least 250000 megalitres would be needed to provide any significant reduction in water level peaks experienced in urban areas. Additionally, reductions in the FSL of this order would not necessarily guarantee reductions in urban flood levels, as the effectiveness of Wivenhoe Dam in reducing urban flood levels is

directly dependent on the distribution of rainfall in the Brisbane River catchment during a flood event (Wivenhoe Dam controls only 50% of the total Brisbane River catchment) and the spacing between individual flood events.

NORTH PINE DAM

North Pine Dam has no flood mitigation potential. Unlike Wivenhoe Dam, once the dam has reached FSL, all water flows into the dam must be released to protect the structural safety of the dam.

Any radial gate operation at North Pine Dam to release flood water, results in inundation of Youngs Crossing Road, so lowering the FSL is problematic and may best be achieved by increasing the daily water diversion to the North Pine Dam Water Treatment Plant. There are river release valves that allow some water to be drained from North Pine Dam without inundating Youngs Crossing. These valves have been operated continuously since the recent gate releases to manage residual inflows into the dam. However outflows from these valves are restricted to flows in the order of several hundred megalitres per day as larger flows will adversely impact on Youngs Crossing. Certainly a small reduction in the level of North Pine Dam is potentially beneficial in preventing closures of Youngs Crossing Road associated with small storm events.

It should be noted however that Youngs Crossing Road is also impacted by uncontrolled flood flows from Lake Kurwongbah and local storm run-off. In recent times Youngs Crossing Road has been closed by flood water during times when no water releases were being made from North Pine Dam, but when storm rains resulted in flood flows from uncontrolled areas of the catchment.

The table below gives an indication of the rainfall required to operate for NPD:

		Capacity		Rainfall Required to Operate		
Level	Capasity			Wet Conditions	Dry Conditions	
	m AHD	%	ML	mm	mm	
FSL	39.60	100.0%	214,302	5	60	
Reduced FSL	39.10	95.0%	203,618	35	100	

Recent changes to the Manual of Flood Mitigation for North Pine Dam allows for some ability to retain up to 2500 megalitres of water to reduce impacts on Youngs Crossing Road, provided favourable weather forecasts are experienced. However the preferred option to reduce public inconvenience associated with storm events would be to raise the flood immunity of the river crossing on Youngs Crossing Road. This crossing is primarily a low level causeway that is potentially unsuitable given the volume of traffic that now uses this crossing on a daily basis.

LESLIE HARRISON DAM

Similar to North Pine Dam, Leslie Harrison Dam has no flood mitigation potential. Once the dam has reached FSL, all water flows into the dam must be released to protect the structural safety of the dam.

The dam is relatively small with a total full supply storage volume of only 24800 megalitres, against an inflow volume during a 72 hour 1 in 50 year storm event of over 30000 megalitres. Flood gate operations at Leslie Harrison Dam do not impact on public roads and generally only inconvenience the general public during large flood events. Reductions in this inconvenience cannot be achieved by small reductions in dam storage

From:

Lance McCallum [Lance.McCallum

Sent:

Saturday, 15 January 2011 10:31 AM

To:

Dan Spiller; Bradley John

Cc: Subject: Tim Watts
Urgent - Cabinet in confidence

John/Dan

The Minister has asked that preparation be done over the weekend that will enable him to go to the Emergncy Cabinet meeting on Monday with a position on how the Govt is going to handle the issues of reviewing operational decisions made by SEQwater and SEQWGM in relation to releases from the dams.

I understand that in further to the recent independent review of the Wivenhoe operations manual the WGM is also undertaking further work by compiling a list of the operational experts who authored the manual.

appy to discuss further.

' nanks, Lance.

This email, together with any attachments, is intended for the named recipient(s) only; and may contain privileged and confidential information. If received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network.

If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and /or publication of this email is also prohibited.

Unless stated otherwise, this email represents only the views of the sender and not the views of the Queensland Government.

Please consider the environment before printing this email.

Suzie Emery Bradley John [John.Bradley From: Sent: Saturday, 15 January 2011 10:34 AM Lance.McCallum To: tim.watts Cc: ; Barry Dennien Subject: Re: Urgent - Cabinet in confidence Thanks Lance - we have anticipated the need for something like this - seqwgm work underway - I will talk to SEOWGM when out of SDMG now on. Regards John B From: Lance McCallum [mailto:Lance.McCallum Sent: Saturday, January 15, 2011 10:30 AM To: spiller daniel @ SEQWGM; Bradley John Cc: Tim Watts <Tim.Watts Subject: Urgent - Cabinet in confidence John/Dan The Minister has asked that preparation be done over the weekend that will enable him to go to the Emergncy Cabinet meeting on Monday with a position on how the Govt is going to handle the issues of reviewing operational decisions made by SEQwater and SEQWGM in relation to releases from the dams. I understand that in further to the recent independent review of the Wivenhoe operations manual the WGM is also undertaking further work by compiling a list of the operational experts who authored the manual. Happy to discuss further. Thanks, Lance.

1 ream of paper = 6% of a tree and 5.4kg CO2 in the atmosphere

3 sheets of A4 paper = 1 litre of water

Think B4U Print

From:

Barry Dennien [Barry.Dennien

Sent:

Saturday, 15 January 2011 10:41 AM

To: Cc: Dan Spiller Elaina Smouha

Subject:

Fwd: Urgent - Cabinet in confidence

Dan elaina

I take it you are on to this

Regards

Barry Dennien

Begin forwarded message:

From: Bradley John < John. Bradley

Date: 15 January 2011 10:33:42 AM AEST

To: "Lance.McCallum

<Lance.McCallum

>, Dan Spiller <<u>Daniel.Spiller</u>

>, Barry Dennien

<tim.watts

Cc: "tim.watts <Barry.Dennier

Subject: Re: Urgent - Cabinet in confidence

Thanks Lance - we have anticipated the need for something like this - seqwgm work underway - I will talk to SEQWGM when out of SDMG now on.

Regards John B

From: Lance McCallum [mailto:Lance.McCallum

Sent: Saturday, January 15, 2011 10:30 AM **To:** spiller daniel **Security**; Bradley John

Cc: Tim Watts < Tim. Watts

Subject: Urgent - Cabinet in confidence

John/Dan

The Minister has asked that preparation be done over the weekend that will enable him to go to the Emergncy Cabinet meeting on Monday with a position on how the Govt is going to handle the issues of reviewing operational decisions made by SEQwater and SEQWGM in relation to releases from the dams.

I understand that in further to the recent independent review of the Wivenhoe operations manual the WGM is also undertaking further work by compiling a list of the operational experts who authored the manual.

Happy to discuss further.

Thanks, Lance.

+	+
Think B4U Print	
1 ream of paper = 6% of a tree and 5.4kg CO2 in the atmosphere	
3 sheets of A4 paper = 1 litre of water	

From:

Sent:

To:

Cc:

Elaina Smouha [elainamir Saturday, 15 January 2011 1:42 PM john.bradley Barry Dennien; Dan Spiller; pborrows

Subject:

Cabinet in confidence - discussion points

Attachments:

Public inquiry strategy - brief.docx

John

Attached are some discussion points for our 2pm teleconference about Monday's Emergency Cabinet meeting.

; bob.reilly

Regards

Elaina

Discussion points for teleconference

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background

- 1) Design of Dam Storages/Spillway upgrade (Responsible: Seqwater)
- 2) How does Wivenhoe Dam work as a flood mitigator? Stats on how much did Wivenhoe Dam knock off the flood peak? [Priority to get out to the public] (Responsible: Segwater)
- 3) Development of Flood Mitigation Manual (Responsible: Seqwater/DERM)
 - a. Four strategies
 - b. History of Flood Mitigation Manual updates and peer review
- 4) Responsibility under the Water Supply (Safety and Reliability) Act 2008 (Responsible: DERM)
 - a. What is the formal reporting process following a major flood event?
- 5) "The Event" operation of Wivenhoe Dam (Responsible: Segwater)
 - a. Event report under the Flood Mitigation Manual
- 6) "The Event" management of the Water Grid emergency under the SEQ Water Grid Emergency Response Plan (Responsible: SEQ Water Grid Manager)
- 7) What next?
 - a. SWOT
 - i. Community feedback
 - ii. A significant (from a national perspective)

Segwater report

Flood Mitigation Manual requires a report to the Chief Executive after a significant flood event, on the effectiveness of the operational procedures:

- Get more comprehensive report from Brian Cooper? review appropriateness of trigger levels – take into account the accuracy of rainfall forecasts provided by BOM at the time – reliability of weather forecasts.
- · Set up expert panel for Flood Mitigation Manual review
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight)

Seqwater to procure review.

Urgent accelerated review due to anticipated further rainfall.

From:

Duty Engineer (dutysed

Sent:

Saturday, 15 January 2011 2:08 PM

To:

'Peter Borrows'; 'Rob Drury'; 'Terry Malone'

Cc:

Dan Spiller; 'John Bradley'; Elaina Smouha; bob.reilly

Subject:

March 2010 Report Index

Attachments:

Report Index.pdf

Follow Up Flag: Flag Status:

Follow up Flagged

ΕΥÍ

Terry Malone Duty Engineer

Flood Operations Centre

Phone:

Fax:

Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).

; Peter Borrows;

From: Peter Borrows [mailto:pborrows

Sent: Saturday, 15 January 2011 1:10 PM **To:** Rob Drury; Duty Seq; Terry Malone

Cc: Peter Borrows

Subject: Fw: 2 pm phone hook up - Wivenhoe operations brief preparation

Rob & Terry, can you both come in on this at 2pm please.

From: Barry Dennien <Barry.Dennien

To: Dan Spiller < Daniel. Spiller >; John Bradley (john. bradley

<john.bradley >; Elaina Smouha <Elaina.Smouha

bob.reilly

<bob.reilly

Sent: Sat Jan 15 12:10:09 2011

Subject: 2 pm phone hook up - Wivenhoe operations brief preparation

Folks

Details of phone hook up:

Agenda to follow in approx one hour

Barry Dennien

received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network. If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and/or publication of this email is also prohibited.

While all care has been taken, the SEQ Water Grid Manager disclaims all liability for loss or damage to person or property arising from this message being infected by a computer virus or other contamination. Unless stated otherwise, this email represents only the views of the sender and not the views of the SEQ Water Grid Manager and/or the Queensland Government.

-----Safe Stamp-----

Your Anti-virus Service scanned this email. It is safe from known viruses. For more information regarding this service, please contact your service provider. Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).

Prepared by:

Doc No.: 942353 Entered:



SunWater Limited ACN 131 034 985

179 Turbot Street, Brisbane PO Box 15536 City East Brisbane Queensland Australia 4002

Tel: +61 7 3120 0153 Fax: +61 7 3120 0242

Author:


Mr Rob Ayre

Headworks Design Manager Infrastructure Development

Approved:

Mr Daryl Brigden

Manager, Engineering South Infrastructure Development



Final Report

Flood Events at Wivenhoe, Somerset and North Pine Dams for February and March 2010

> Date: June 2010 P-AEXP-1802-AK-01-03 File: 08-007969/00

Prepared for: Seqwater

This report has been produced by SunWater, to provide information for client use only.

The information contained in this report is limited by the scope and the purpose of the engineering study, and should not be regarded as completely exhaustive. Permission to use or quote information from this report in studies external to the Consortion gust first be obtained from the Chief Executive, SunWater.



TABLE OF CONTENTS

1.0	INTRODUCTION	
2.0	FLOOD EVENT SUMMARY	
2.1	FEBRUARY 2010	
2.2		
3.0	MOBILISATION AND STAFFING	
3.1	16 TH TO 18 TH FEBRUARY 2010	
3.2	1 ST TO 4 TH MARCH	
3.3	5 TH TO 6 TH MARCH	
3.4	6 TH TO 7 TH MARCH	
3.5	10 TH TO 11 TH MARCH	
4.0	EVENT RAINFALL	
4.1	FEBRUARY 2010	
4.2	MARCH 2010	
5.0	INFLOW AND RELEASE DETAILS	12
5.1	16 TH TO 18 TH FEBRUARY 2010	
5.2	1 ST MARCH 2010	15
5.3	6 / 7 TH MARCH 2010	
5.4	11 TH MARCH 2010	21
6.0	DATA COLLECTION SYSTEM PERFORMANCE	25
6.1	NETWORK AVAILABILITY	25
6.2	RAINFALL	25
6.3	STREAM HEIGHT	
6,3	3.1 Main Stream	26
6.	3.2 Back-up Stream	27
	3.3 Headwater Sensors	
-	3.4 Sensor Calibration	
	3.5 Stream Height Rating Curves	
7.0	DATA ANALYSIS PERFORMANCE	
7.1	RUNOFF-ROUTING MODELS	
7.2	BASEFLOW ASSESSMENT	
8.0	COMMUNICATIONS	
8.1	EVENT LOG	
8.2	DECLARATION OF EVENT MOBILISATION	.,,31



8.3	SHIFT HANDOVER	32
9.0 F	LOOD MANAGEMENT STRATEGIES	33
9.1	16 TH TO 18 TH FEBRUARY 2010	33
9.1.1	North Pine Dam	33
9.2	26 TH FEBRUARY TO 4 TH MARCH	35
9.2.1	Somerset and Wivenhoe Dam	35
9.2.2	North Pine Dam	38
9.3	4 TH MARCH TO 7 TH MARCH	41
9.3.1	North Pine Dam	
9.4	10 TH MARCH TO 11 TH MARCH	44
9.4.1	North Pine Dam	44
10.0 R	ECOMMENDATIONS & CONCLUSIONS	46
10.1	DATA COLLECTION	46
10.2	DATA ANALYSIS	46
10.3	DIRECTIVES AND STATUS REPORTS	46
10.4	OPERATIONAL STRATEGIES	47

LIST OF APPENDICES

APPENDIX A - FOC Attendance Logs & Event Logs

APPENDIX B - Estimated Inflows and Release

APPENDIX C - Reservoir Headwater Levels

From:

Dan Spiller [Daniel.Spiller

Sent:

Saturday, 15 January 2011 2:14 PM

To:

'watergridmedia

Subject:

FW: March 2010 Report Index

Attachments:

Report Index.pdf

From: Duty Engineer [mailto:dutysed

Sent: Saturday, January 15, 2011 2:08 PM **To:** 'Peter Borrows'; 'Rob Drury'; 'Terry Malone'

Cc: Dan Spiller; 'John Bradley'; Elaina Smouha; bob.reilly

Subject: March 2010 Report Index

FYI

Terry Malone Duty Engineer

Flood Operations Centre



Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).

From: Peter Borrows [mailto:pborrows

Sent: Saturday, 15 January 2011 1:10 PM **To:** Rob Drury; Duty Seq; Terry Malone

Cc: Peter Borrows

Subject: Fw: 2 pm phone hook up - Wivenhoe operations brief preparation

Rob & Terry, can you both come in on this at 2pm please.

From: Barry Dennien <Barry.Dennien

<john.bradley</p>
>; Elaina Smouha < Elaina.Smouha</p>
>; Peter Borrows;
bob.reilly

bob.reilly bob.reilly bob.Sent: Sat Jan 15 12:10:09 2011

Subject: 2 pm phone hook up - Wivenhoe operations brief preparation

Folks

Details of phone hook up:



Agenda to follow in approx one hour

Barry Dennien

This email, together with any attachments, is intended for the named recipient(s) only; and may contain privileged and confidential information. You understand that any privilege or confidentiality attached to this message is not waived, lost or destroyed because you have received this message in error. If received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network. If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and/or publication of this email is also prohibited.

While all care has been taken, the SEQ Water Grid Manager disclaims all liability for loss or damage to person or property arising from this message being infected by a computer virus or other contamination. Unless stated otherwise, this email represents only the views of the sender and not the views of the SEQ Water Grid Manager and/or the Queensland Government.

-----Safe Stamp-----

Your Anti-virus Service scanned this email. It is safe from known viruses. For more information regarding this service, please contact your service provider. Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).

Prepared by:

Doc No.: 9 나 2 3 5 3 Entered:



SunWater Limited ACN 131 034 985

179 Turbot Street, Brisbane PO Box 15536 City East Brisbane Queensland Australia 4002

Tel: +61 7 3120 0153 Fax: +61 7 3120 0242

Author:


Mr Rob Ayre

Headworks Design Manager Infrastructure Development

Approved:

Mr Daryl Brigden

Manager, Engineering South Infrastructure Development



Final Report

Flood Events at Wivenhoe, Somerset and North Pine Dams for February and March 2010

> Date: June 2010 P-AEXP-1802-AK-01-03 File: 08-007969/00+

Prepared for: Segwater

This report has been produced by SunWater, to provide information for client use only.

The information contained in this report is limited by the scope and the purpose of the engineering study, and should not be regarded as completely exhaustive.

Permission to use or quote information from this report in studies external to the Comparison first be obtained from the Chief Executive, SunWater.



TABLE OF CONTENTS

1.0	INTRODUCTION
2.0	FLOOD EVENT SUMMARY
2.1	FEBRUARY 20102
2.2	MARCH 2010
3.0	MOBILISATION AND STAFFING
3.1	16 TH TO 18 TH FEBRUARY 20105
3.2	1 ST TO 4 TH MARCH5
3,3	5 TH TO 6 TH MARCH
3.4	6 TH TO 7 TH MARCH6
3.5	10 TH TO 11 TH MARCH6
4.0	EVENT RAINFALL
4.1	FEBRUARY 20107
4.2	MARCH 2010g
5.0	INFLOW AND RELEASE DETAILS12
5.1	16 TH TO 18 TH FEBRUARY 201012
5.2	1 ST MARCH 201015
5.3	6 / 7 TH MARCH 201018
5.4	11 TH MARCH 201021
6.0	DATA COLLECTION SYSTEM PERFORMANCE25
6.1	NETWORK AVAILABILITY25
6.2	RAINFALL25
6.3	STREAM HEIGHT26
6.3	.1 Main Stream
6.3	
6.3	
6.3	
6.3	
7.0	DATA ANALYSIS PERFORMANCE29
7.1	RUNOFF-ROUTING MODELS29
7.2	BASEFLOW ASSESSMENT29
8.0	COMMUNICATIONS31
8.1	EVENT LOG31
8.2	DECLARATION OF EVENT MOBILISATION31



8.3	SHIFT HANDOVER	32
9.0 F	LOOD MANAGEMENT STRATEGIES	
9.1	16 TH TO 18 TH FEBRUARY 2010	33
9.1.1	North Pine Dam	33
9.2	26 TH FEBRUARY TO 4 TH MARCH	35
9.2.1	Somerset and Wivenhoe Dam	
9.2.2	North Pine Dam	38
9.3	4 TH MARCH TO 7 TH MARCH	41
9.3.1	North Pine Dam	41
9.4	10 TH MARCH TO 11 TH MARCH	44
9.4.1	North Pine Dam	
10.0 R	ECOMMENDATIONS & CONCLUSIONS	46
10.1	DATA COLLECTION	46
10.2	DATA ANALYSIS	46
10.3	DIRECTIVES AND STATUS REPORTS	46
10.4	OPERATIONAL STRATEGIES	47

LIST OF APPENDICES

APPENDIX A - FOC Attendance Logs & Event Logs

APPENDIX B - Estimated Inflows and Release

APPENDIX C - Reservoir Headwater Levels

From:

Sent:

Dan Spiller [Daniel.Spiller Saturday, 15 January 2011 2:21 PM

To:

'Duty Engineer'

Subject:

FW: Cabinet in confidence - discussion points

Attachments:

Public inquiry strategy - brief.docx

Follow Up Flag: Flag Status:

Follow up Flagged

From: Elaina Smouha [mailto:elainamir

Sent: Saturday, January 15, 2011 1:42 PM

To: john.bradley

Cc: Barry Dennien; Dan Spiller; pborrows

; bob.reilly

Subject: Cabinet in confidence - discussion points

John

Attached are some discussion points for our 2pm teleconference about Monday's Emergency Cabinet meeting.

Regards

Elaina

Discussion points for teleconference

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- d) Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background

- 1) Design of Dam Storages/Spillway upgrade (Responsible: Seqwater)
- 2) How does Wivenhoe Dam work as a flood mitigator? Stats on how much did Wivenhoe Dam knock off the flood peak? [Priority to get out to the public] (Responsible: Segwater)
- 3) Development of Flood Mitigation Manual (Responsible: Seqwater/DERM)
 - a. Four strategies
 - b. History of Flood Mitigation Manual updates and peer review
- 4) Responsibility under the Water Supply (Safety and Reliability) Act 2008 (Responsible: DERM)
 - a. What is the formal reporting process following a major flood event?
- 5) "The Event" operation of Wivenhoe Dam (Responsible: Seqwater)
 - a. Event report under the Flood Mitigation Manual
- 6) "The Event" management of the Water Grid emergency under the SEQ Water Grid Emergency Response Plan (Responsible: SEQ Water Grid Manager)
- 7) What next?
 - a. SWOT
 - i. Community feedback
 - ii. A significant (from a national perspective)

Segwater report

Flood Mitigation Manual requires a report to the Chief Executive after a significant flood event, on the effectiveness of the operational procedures:

- Get more comprehensive report from Brian Cooper? review appropriateness of trigger levels – take into account the accuracy of rainfall forecasts provided by BOM at the time – reliability of weather forecasts.
- Set up expert panel for Flood Mitigation Manual review
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight)

Seqwater to procure review.

Urgent accelerated review due to anticipated further rainfall.

From:

Sent:

To:

Elaina Smouha [elainamir Saturday, 15 January 2011 4:37 PM Barry Dennien; Dan Spiller; Michael Lyons Ministerial brief - outline Ministerial brief - contents outline.docx

Subject:

Attachments:

Discussion points for teleconference

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- d) Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background (focus on Brisbane River flooding issues)

- Design of Dam Storages/Spillway upgrade (Information provider: Seqwater and Peter Allen DERM) [1/3 to ½ a page]
- 2) "The Flood Event" Q&A (Information provider: Seqwater) [2 ½ pages]
 - a. Chronology High level time step of events and significant decision making/changes
 more detailed time step information for Tuesday afternoon (i.e. what was the
 BOM forecast at the time, narrow peak etc.)
 - b. How does Wivenhoe Dam work as a flood mitigator?
 - c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?
 - d. Statistics on how much did Wivenhoe Dam knock off the flood peak.
 - e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?
 - f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?
 - g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)
 - h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
 - i. What is the fuse plug and why did it need to be maintained?
 - j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?
 - k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

- 3) The Flood Mitigation Manual (Information Provider: Segwater/DERM) [½ to 1 page]
 - a. Describe the decision making framework Four strategies
 - b. How is the Manual designed to work?
 - c. History of Flood Mitigation Manual updates and peer review who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?
 - Attach Minister Robertson's request for advice on pre-emptive release and our response (Information provider: SEQ Water Grid Manager)
- 4) Regulatory context Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen DERM)
 - a. Flood Mitigation Manual approval
 - b. Formal reporting process under the Flood Mitigation Manual attach report resulting from the February 1999 flood event
 - c. Decision making process under the Flood Mitigation Manual
 - i. Who makes the flood release decisions under the Manual?
 - ii. who is informed/consulted?
 - iii. effect of the recent Flood Communication Protocol?
- 5) Brian Cooper Flood Mitigation Manual compliance review (*Responsible: SEQ Water Grid Manager*)

Seqwater report

(Information provider: Seqwater, Peter Allen and Bob Reilly)

Seqwater, in consultation with Peter Allen and Bob Reilly, to set out how Seqwater's Flood Mitigation Manual Report to the Chief Executive on the effectiveness of the operational procedures will be undertaken.

- Attach table of contents of the 1999 Flood Mitigation Manual report
- Reflect Brian Cooper's compliance review
- Peer review establishment of an expert panel who will be on it? Peter Allen and Bob Reilly may provide some input.
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight?)

Timeframes on the development of the report – consider urgency due to anticipated further rainfall during this summer.

zie Emery

. rom:

Elaina Smouha [elainamir

Sent:

Saturday, 15 January 2011 5:03 PM

To:

Cc:

mfoster ; peter.allen

pborrows; rdrury

john.bradley

bob.reilly ; Barry Dennien; Dan Spiller; Michael Lyons; Elaina

Smouha

Subject:

Cabinet in confidence - Ministerial brief outline

Attachments:

Ministerial brief - contents outline.docx

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

ı; dutyseq

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance SEQ Water Grid Manager

Email: elaina.smouha

Visit: Level 15, 53 Albert Street Brisbane Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

Ministerial brief outline

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- d) Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background (focus on Brisbane River flooding issues)

- 1) Design of Dam Storages/Spillway upgrade (Information provider: Seqwater and Peter Allen DERM) [1/3 to ½ a page]
- 2) "The Flood Event" Q&A (Information provider: Segwater) [2 ½ pages]
 - a. Chronology High level time step of events and significant decision making/changes
 more detailed time step information for Tuesday afternoon (i.e. what was the
 BOM forecast at the time, narrow peak etc.)
 - b. How does Wivenhoe Dam work as a flood mitigator?
 - c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?
 - d. Statistics on how much did Wivenhoe Dam knock off the flood peak.
 - e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?
 - f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?
 - g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)
 - h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
 - i. What is the fuse plug and why did it need to be maintained?
 - j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?
 - k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

- 3) The Flood Mitigation Manual (Information Provider: Seqwater/DERM) [1/2 to 1 page]
 - a. Describe the decision making framework Four strategies
 - b. How is the Manual designed to work?
 - c. History of Flood Mitigation Manual updates and peer review who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?
 - d. Attach Minister Robertson's request for advice on pre-emptive release and our response (Information provider: SEQ Water Grid Manager)
- 4) Regulatory context Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen DERM)
 - a. Flood Mitigation Manual approval
 - b. Formal reporting process under the Flood Mitigation Manual attach report resulting from the February 1999 flood event
 - c. Decision making process under the Flood Mitigation Manual
 - i. Who makes the flood release decisions under the Manual?
 - ii. who is informed/consulted?
 - iii. effect of the recent Flood Communication Protocol?
- 5) Brian Cooper Flood Mitigation Manual compliance review (*Responsible: SEQ Water Grid Manager*)

Segwater report

(Information provider: Seqwater, Peter Allen and Bob Reilly)

Seqwater, in consultation with Peter Allen and Bob Reilly, to set out how Seqwater's Flood Mitigation Manual Report to the Chief Executive on the effectiveness of the operational procedures will be undertaken.

- · Attach table of contents of the 1999 Flood Mitigation Manual report
- Reflect Brian Cooper's compliance review
- Peer review establishment of an expert panel who will be on it? Peter Allen and Bob Reilly may provide some input.
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight?)

Timeframes on the development of the report – consider urgency due to anticipated further rainfall during this summer.

From:

peter_allen

Sent:

Sunday, 16 January 2011 11:58 AM

To:

Cc:

rdrury pborrows

john.bradley

Barry Dennien; daniel

dutyseq

bob.reilly

michael.lyons

elaina.smouha

peter.allen

mfoster

threereillys

Re: Fw: Cabinet in confidence - Ministerial brief outline - Regulatory context

Attachments:

Regulatory context for the dams.doc

Barry,

Subject:

This is the proposed regiulatory context to go into the Ministerial Briefing. Both Bob Reilly and Peter Borrows have reviewed it and are happy with it.

> wrote:

Peter Allen

Director Dam Safety (Water Supply)

> Allen Peter < Peter. Allen

DERM

	>	
	>	
	>	
	>	Original Message
	>	From: Elaina Smouha <elainamir< th=""></elainamir<>
		To: mfoster <mfoster>; Allen Peter;</mfoster>
		Reilly Bob; pborrows <pborrows>; rdrury >; rdrury</pborrows>
		<pre><rdrury< th=""></rdrury<></pre>
		Cc: Bradley John; Dennien Barry ; spiller daniel ; Lyons
		Michael ; smouha elaina
		Sent: Sat Jan 15 17:02:53 2011
		Subject: Cabinet in confidence - Ministerial brief outline
	>	Door All
	<i>></i>	Dear All
	-	To assist, attached is a Ministerial brief outline as per our recent
-		teleconference, for Monday's Emergency Cabinet meeting. It also records
<u>:</u>		those who will be providing information for the Background and Flood
		Mitigation Manual report process.
	>	Theightion Fidinal report process,
	-	As discussed, the brief needs to be provided to Minister Robertson
		tomorrow (Sunday, 16 January 2011).
	>	
	>	Regards
	>	-
	>	Elaina
	>	
	>	
	>	
	>	Elaina Smouha
	>	
		Director, Governance and Regulatory Compliance
	>	070 11 1 0 11 11
		SEQ Water Grid Manager
	>	
	_ >	
	_	

Regulatory context for the dams' flood operations

These are contained in the Flood Mitigation Manual (manual) approved under sections 370 to 374 of the *Water Supply (Safety and Reliability) Act 2008.* The Chief Executive Officer (CEO) of DERM (or his delegate) approves the manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Act for the CEO to take into account when approving the manual.

The manual for the dams requires, amongst other matters:

- a) Flood operations to be conducted in accordance with manual's provisions.
 (There is an approval process specified in the manual, if Seqwater considers a different flood release strategy is desirable to deal with a particular flood event.
 This was not used in the January 2011 flood event)
- b) Flood operations to be under the control of CEO-approved engineers (who are highly qualified and experienced)
- c) Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- d) Reporting on the flood operations during flood events.
- e) Reviews after flood events such as the January 2011 event. For this flood event, the Queensland Government engaged Mr Brian Cooper, an independent consulting engineer, to review compliance with the manual. Mr Cooper concluded (Attachment??):
 - "...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded..." (p.3 of the final report or other appropriate reference??)

The manual is separate from a draft communication protocol (Insert name) between the Local, State and Commonwealth government agencies that are affected by the dams' flood operations. This protocol is not binding on the parties to it is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Seqwater activates to manage such events. None of them are involved in any of the regulatory decisions concerning the dams or are members of the work unit (Office of the Water Supply Regulator) which undertakes the CEO's regulatory functions.

From:

Barry Dennien [Barry.Dennien

Sent:

Sunday, 16 January 2011 12:25 PM

To:

Dan Spiller

Subject:

Attachments:

Fwd: Cabinet in confidence - Ministerial brief outline -

Regulatory context for the dams.doc; ATT00001.htm

Regulatory context

Regards

Barry Dennien

Begin forwarded message:

From: "peter allen " <peter aller Date: 16 January 2011 11:57:56 AM AEST To: "rdrury ' <rdrury , "pborrows ' <<u>dutyseq</u> <pborrows "dutyseq "john.bradley ' < john.bradley >, Barry Dennien <Barry.Dennien >, "<u>daniel</u> ' <daniel "michael.lyons elaina.smouha <michael.lyons elaina.smouha "peter.allen <peter.allen</pre> "mfoster <mfoster >, "bob.reilly
bob.reilly ' <<u>threereill</u>ys Cc: "threereillys

Subject: Re: Fw: Cabinet in confidence - Ministerial brief outline - Regulatory context

Barry,

This is the proposed regiulatory context to go into the Ministerial Briefing. Both Bob Reilly and Peter Borrows have reviewed it and are happy with it.

Peter Allen
Director Dam Safety (Water Supply)
DERM

Allen Peter < Peter. Aller

---- Original Message -----

From: Elaina Smouha < elainamir

To: <u>mfoster</u> >; Allen Peter;

Reilly Bob; pborrows pborrows

rdrury

<rdrury >; <u>dutysec</u> <dutysec Cc: Bradley John; Dennien Barry spiller daniel Lyons Michael ; smouha elaina

Sent: Sat Jan 15 17:02:53 2011

Subject: Cabinet in confidence - Ministerial brief outline

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance

SEQ Water Grid Manager

Email: elaina.smouha@ <mailto:elaina.smouha

Visit: Level 15, 53 Albert Street Brisbane

Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

+	+
Think B4U Print	,
1 ream of paper = 6% of a tree and 5.4kg CO2 in t	he atmosphere
3 sheets of A4 paper = 1 litre of water	
<u> </u>	_1_

Regulatory context for the dams' flood operations

These are contained in the Flood Mitigation Manual (manual) approved under sections 370 to 374 of the *Water Supply (Safety and Reliability) Act 2008*. The Chief Executive Officer (CEO) of DERM (or his delegate) approves the manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Act for the CEO to take into account when approving the manual.

The manual for the dams requires, amongst other matters:

- a) Flood operations to be conducted in accordance with manual's provisions. (There is an approval process specified in the manual, if Seqwater considers a different flood release strategy is desirable to deal with a particular flood event. This was not used in the January 2011 flood event)
- b) Flood operations to be under the control of CEO-approved engineers (who are highly qualified and experienced)
- c) Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- d) Reporting on the flood operations during flood events.
- e) Reviews after flood events such as the January 2011 event. For this flood event, the Queensland Government engaged Mr Brian Cooper, an independent consulting engineer, to review compliance with the manual. Mr Cooper concluded (Attachment??):
 - "...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded..." (p.3 of the final report or other appropriate reference??)

The manual is separate from a draft communication protocol (Insert name) between the Local, State and Commonwealth government agencies that are affected by the dams' flood operations. This protocol is not binding on the parties to it is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Sequater activates to manage such events. None of them are involved in any of the regulatory decisions concerning the dams or are members of the work unit (Office of the Water Supply Regulator) which undertakes the CEO's regulatory functions.

Suzie Emery

From:

Sent:

Bradley John [John.Bradley Sunday, 16 January 2011 12:55 PM

To:

Barry Dennien; Dan Spiller

Subject:

RE: Should the Wivenhoe have been bigger? | Courier Mail Andrew Bolt Blog

Barry

Can you pls ask Peter B to add this question to the BN today

Is it true Wivenhoe didn't comply with ANCOLD standard?

Why didn't you implement recommendations of the 2007 report?

John Bradley Director-General

Department of Environment and Resource Management

Email: John.Bradley www.derm.gld.gov.au

Department of Environment and Resource Management 400 George Street, Brisbane Q 4000 GPO Box 2454, Brisbane Q 4001

From: Barry Dennien [mailto:Barry.Dennien

Sent: Sunday, 16 January 2011 7:25 AM To: spiller daniel ; Bradley John

Subject: Fwd: Should the Wivenhoe have been bigger? | Courier Mail Andrew Bolt Blog

For note

Regards

Barry Dennien

Begin forwarded message:

From: Barry Dennien < Barry. Dennien

Date: 16 January 2011 7:00:05 AM AEST

To: Peter Borrows <pborrows

Subject: Should the Wivenhoe have been bigger? | Courier Mail Andrew Bolt

Blog

http://blogs.news.com.au/couriermail/andrewbolt/index.php/couriermail/comments/sh ould the wivenhoe have been bigger/

Peter

It may be worthwhile starting to gather all dam studies and reports

Note this blog is selectively picking bits of information from the 2007 report

Talk later

Barry

Regards Barry Dennien

This email, together with any attachments, is intended for the named recipient(s) only; and may contain privileged and confidential information. You understand that any privilege or confidentiality attached to this message is not waived, lost or destroyed because you have received this message in error. If received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from

message in error, if received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network. If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and/or publication of this email is also prohibited.

While all care has been taken, the SEQ Water Grid Manager disclaims all liability for loss or damage to person or property arising from this message being infected by a computer virus or other contamination. Unless stated otherwise, this email represents only the views of the sender and not the views of the SEQ Water Grid Manager and/or the Queensland Government.

	•
Think B4U Print	
1 ream of paper = 6% of a tree and 5.4kg CO2 in the atmosphere	e
3 sheets of A4 paper = 1 litre of water	
+	

Suzie Emery

From:

Lance McCallum [Lance.McCallum

Sent:

Sunday, 16 January 2011 2:45 PM

To:

Bradley John; Dan Spiller; Barry Dennien; Hunt Dan

Cc:

Kirstie Ross; Tim Watts; Geoff Stead

Subject:

Special cabinet Meeting - Monday 17 January 2010 - Pre Brief

Confidential

John, Dan('s), Barry

I confirm a pre-cabinet briefing tomorrow morning from 9am in Minister Robertson's boardroom.

Thanks

Lance.

This email, together with any attachments, is intended for the named recipient(s) only; and may contain privileged and confidential information. If received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network.

If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and /or publication of this email is also prohibited.

Unless stated otherwise, this email represents only the views of the sender and not the views of the Queensland Government.

Please consider the environment before printing this email.

Suzie Emery

From:

Peter Borrows (pborrows

Sent:

Sunday, 16 January 2011 3:59 PM

To:

bob.reilly

; Rob Drury; Duty Seq; john.bradley Dennien; Dan Spiller

; Barry

Cc: Subject: Michael Lyons; Mike Foster; Elaina Smouha; peter.allen Cabinet in confidence - Ministerial brief outline

Attachments:

Ministerial brief - contents outline.docx

Please see attached draft with attachment.

In relation to the draft contents outline sent yesterday, the following is a cross reference FYI.

Regards, Peter.

Peter Borrows

Chief Executive Officer

Queensland Bulk Water Supply Authority trading as Seqwater



E phorrows

Level 3, 240 Margaret St, Brisbane City QLD 4000

PO Box 16146, City East QLD 4002 Website | www.segwater.com.au



Swimming in weirs and fast

From: Elaina Smouha [mailto:elainamir

Sent: Saturday, 15 January 2011 5:03 PM

To: Mike Foster; peter.allen

; bob.reilly ; Peter Borrows; Rob Drury; Duty Seq

; daniel.spiller

Cc: john.bradley michael.lyons

; barry.dennien ; Elaina Smouha

Subject: Cabinet in confidence - Ministerial brief outline

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance SEQ Water Grid Manager

Email: elaina.smouha

, š

Visit: Level 15, 53 Albert Street Brisbane Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

Your Anti-virus Service scanned this email. It is safe from known viruses. For more information regarding this service, please contact your service provider. Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).

Ministerial brief outline

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- d) Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background (focus on Brisbane River flooding issues)

- 1) Design of Dam Storages/Spillway upgrade (Information provider: Seqwater and Peter Allen DERM) [1/3 to ½ a page]
- 2) "The Flood Event" Q&A (Information provider: Seqwater) [2 ½ pages]
 - a. Chronology High level time step of events and significant decision making/changes

 more detailed time step information for Tuesday afternoon (i.e. what was the
 BOM forecast at the time, narrow peak etc.)
 - b. How does Wivenhoe Dam work as a flood mitigator?
 - c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?
 - d. Statistics on how much did Wivenhoe Dam knock off the flood peak.
 - e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?
 - f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?
 - g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)
 - h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
 - i. What is the fuse plug and why did it need to be maintained?
 - j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?
 - k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

- 3) The Flood Mitigation Manual (Information Provider: Segwater/DERM) [1/2 to 1 page]
 - a. Describe the decision making framework Four strategies
 - b. How is the Manual designed to work?
 - c. History of Flood Mitigation Manual updates and peer review who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?
 - d. Attach Minister Robertson's request for advice on pre-emptive release and our response (*Information provider: SEQ Water Grid Manager*)
- 4) Regulatory context Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen DERM)
 - a. Flood Mitigation Manual approval
 - b. Formal reporting process under the Flood Mitigation Manual attach report resulting from the February 1999 flood event
 - c. Decision making process under the Flood Mitigation Manual
 - i. Who makes the flood release decisions under the Manual?
 - ii. who is informed/consulted?
 - iii. effect of the recent Flood Communication Protocol?
- 5) Brian Cooper Flood Mitigation Manual compliance review (*Responsible: SEQ Water Grid Manager*)

Seqwater report

î

(Information provider: Sequater, Peter Allen and Bob Reilly)

Seqwater, in consultation with Peter Allen and Bob Reilly, to set out how Seqwater's Flood Mitigation Manual Report to the Chief Executive on the effectiveness of the operational procedures will be undertaken.

- Attach table of contents of the 1999 Flood Mitigation Manual report
- Reflect Brian Cooper's compliance review
- Peer review establishment of an expert panel who will be on it? Peter Allen and Bob Reilly may provide some input.
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight?)

Timeframes on the development of the report – consider urgency due to anticipated further rainfall during this summer.

Suzie Emery

From:

Sent: To:

Subject: Attachments:

Elaina Smouha [elainaming Sunday, 16 January 2011 4:07 PM Dan Spiller; Barry Dennien Cabinet in confidence - Regulatory context Regulatory_context_for_the_dams[1].docx

I have tracked my changes.

Elaina

Regulatory context for the dams' flood operations

TheseOperational procedures for flood mitigation for a dam are contained in the Flood Mitigation Manual-(manual) approved under sections 370 to 374 of the Water Supply (Safety and Reliability) Act 2008 (Water Supply Act). Under section 370 of the Water Supply Act, Seqwater as the owner and operator of Wivenhoe and Somerset Dams is required to prepare a Flood Mitigation Manual. The Chief Executive Officer-(CEO) of DERM (or his delegate) approves the manual Flood Mitigation Manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Water Supply Act for the CEO to take into account when approving the Flood Mitigation mManual.

The manual for the dams Flood Mitigation Manual requires, amongst other matters:

- a) Flood operations to be conducted in accordance with manual's provisions, unless Seqwater considers that it is necessary to depart from the procedures of the Flood Mitigation Manual to meet the flood mitigation objectives of the Flood Mitigation Manual.. (There is an approval process specified in the manual, if Seqwater considers a different flood release strategy is desirable to deal with a particular flood event. This discretion was not used exercised in the January 2011 flood event).
- b) Flood operations to be under the control of CEO-approved engineers (who are highly qualified and experienced)
- c) Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- d) Reporting on the flood operations during flood events.
- e) Reviews after flood events such as the January 2011 event, and a Seqwater report containing details of the procedures used, the reasons for such and other pertinent information. Seqwater must forward this report to the CE within six weeks of the completion of a flood event. For this flood-event, the Queensland Government engaged Mr Brian Cooper, an independent consulting engineer, to review compliance with the manual. Mr Cooper concluded (Attachment??):
- e) "...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded..." (p.3 of the final report or other appropriate reference??)

Section 374 of the Water Supply Act protects the CE and Sequenter from liability for complying with the Flood Mitigation Manual. It states:

(1) The chief executive or a member of the council does not incur civil liability for an act done, or omission made, honestly and without negligence under this part.

(2) An owner of a dam who observes the operational procedures in a flood mitigation manual, approved by the chief executive, for the dam does not incur civil liability for an act done, or omission made, honestly and without negligence in observing the procedures.

During November 2010, Commonwealth, State and local government agencies developed a Protocol for Communication of Flooding Information for the Brisbane River Catchment – including Floodwater Releases from Wivenhoe and Somerset Dams to "ensure the provision of consistent and robust information to the community". This is separate from the Flood Mitigation Manual, The manual is separate from a draft communication protocol (Insert name) between the Local, State and Commonwealth government agencies that are affected by the dams' flood operations. This protocol is not legally binding on the parties to itand is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Seqwater activates to manage such events in accordance with the Flood Mitigation Manual. The Flood Operations Centre is Nene of them are not involved in any of the regulatory decisions concerning the dams or are members of the work unit (Office of the Water Supply Regulator, Department of Environment and Resource Management,) which undertakes the CEO's regulatory functions.

Suzie Emery

From:

Peter Borrows [pborrows

Sent:

Sunday, 16 January 2011 4:28 PM

To:

bob.reilly ; Rob Drury; Duty Seg; john.bradley

: Barry

Dennien; Dan Spiller

Cc:

Michael Lyons; Mike Foster; Elaina Smouha; peter allen

Subject:

Cabinet in co nfidence - Ministerial brief outline

Attachments:

Ministerial brief - contents outline.docx; Ministerial Briefing Note January 17 2011 Final

Draft for distribution.doc; Jan 2011 Flood Event_Ver 1_draft for distribution.docx

Please see attached draft with attachment.

In relation to the draft contents outline sent yesterday, the following is a cross reference FYI.

The attached Ministerial Briefing Note addresses the questions contained in the Ministerial Information Request as follows:

1) Design of Dam - Storages/Spillway upgrade

Refer Section 1

- 2) "The Flood Event" Q&A
 - a. Chronology High level time step of events and significant decision making/changes more detailed time step information for Tuesday afternoon (i.e. what was the BOM forecast at the time, narrow peak etc.)

Refer Section 2.5

b. How does Wivenhoe Dam work as a flood mitigator?

Refer Sections 2.1, 2.3 and 3.1

c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?

Refer Sections 3.1 and 3.2

d. Statistics on how much did Wivenhoe Dam knock off the flood peak.

Refer Section 2.1

e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?

Refer Sections 2.1 and 2.2

f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?

Refer Section 2.4

g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)

Refer Section 2.4

h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Refer Section 2.2

i. What is the fuse plug and why did it need to be maintained?

Refer Section 2.3

j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?

Refer Section 2.4

k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

Refer Section 2.4

3) The Flood Mitigation Manual

Refer Section 3.1

a. Describe the decision making framework - Four strategies

Refer Section 3.2

b. How is the Manual designed to work?

Refer Section 3.2

c. History of Flood Mitigation Manual updates and peer review – who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?

Refer Section 3.1

4) Regulatory context - Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen - DERM)

Refer Section 4

Regards, Peter.

Peter Borrows


Chief Executive Officer
Queensland Bulk Water Supply Authority trading as Seqwater



E pborrows

Level 3, 240 Margaret St, Brisbane City QLD 4000 PO Box 16146, City East QLD 4002 Website | www.seqwater.com.au





From: Elaina Smouha [mailto:elainamir

Sent: Saturday, 15 January 2011 5:03 PM

To: Mike Foster; peter.allen ; bob.reilly ; bob.reilly ; Peter Borrows; Rob Drury; Duty Seq

Cc: john.bradley ; barry.dennien ; daniel.spiller

michael.lyons Elaina Smouha

Subject: Cabinet in confidence - Ministerial brief outline

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance

SEQ Water Grid Manager


Email: elaina.smouha

Visit: Level 15, 53 Albert Street Brisbane Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

-----Safe Stamp------

Your Anti-virus Service scanned this email. It is safe from known viruses. For more information regarding this service, please contact your service provider. Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).



SeqWaterforlife

JANUARY 2011 FLOOD EVENT



TABLE OF CONTENTS

1	IN'	TRODUCTION	1
2	WI	VENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS	2
	2.1	Flood Mitigation	2
	2.2	Flood Operations	3
3	MA	ANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS	4
4	JA	NUARY 2011 FLOOD EVENT	6
	4.1	Background	6
	4.2	Event Decision Making	7
	4.3	Flood Mitigation Benefits of Wivenhoe Dam	10
5	EV	/ENT REVIEW	12



1 INTRODUCTION

Wivenhoe Dam was constructed by the Queensland Government between 1977 and 1984. The dam is a 56 m AHD high and 2.3 kilometre long earth and rock embankment separated into two parts by a concrete gravity spillway. The spillway is controlled by 5 radial gates, each 12.0 metres wide by 16.0 m AHD high. Two saddle dam embankments are located on the left side of the reservoir.

The dam spillway capacity was upgraded in 2005. This was done primarily through the construction of a 164 metre wide secondary spillway through the right abutment of the existing dam. This spillway contains three erodible earth fill fuse plug embankments that are initiated at different dam levels in excess of EL 75.6.

The dam has two main functions by providing:

- A 1,165,000 ML storage at full supply level (FSL EL 67.0) providing an urban water supply for Brisbane and surrounding areas;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1,450,000 ML up to EL77 (this flood level was increased as part the 2005 upgrade to allow a water level of EL80m and a temporary flood storage volume of 1,966,000 ML with all fuse plugs initiated and the dam at the point of failure).

The dam has an EXTREME hazard classification under ANCOLD guidelines because of the significant development downstream in the Brisbane and Ipswich metropolitan areas, with the population at risk in the event of a dam failure numbering in the hundreds of thousands.

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam is scheduled to occur prior to 2035 to enable the dam to safely pass the Probable Maximum Flood. This work will involve the reconstruction of Saddle Dam 2 as a fuse plug spillway.

Wivenhoe Dam is in excellent condition. Comprehensive Dam Safety reviews undertaken in accordance with ANCOLD guidelines have been undertaken in 1997 (Gutteridge, Haskins & Davey Pty Ltd), 2003 (Wivenhoe Alliance), 2006 (NSW Department of Commerce), 2009 (GHD) and September 2010 (Seqwater). The reports concluded that the design of the dam is in accordance with modern day standards and that there are no significant outstanding design or construction issues that require investigation.



2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 Flood Mitigation

The Brisbane River catchment covers an area of approximately 14,000 square kilometres of which about half is below Wivenhoe Dam. Maximum overall flood mitigation effect is achieved by operating Wivenhoe Dam in conjunction with Somerset Dam. Although Somerset and Wivenhoe Dam reduce flooding in Brisbane City, major flooding can still occur. The Lockyer-Laidley Valley drains into the Brisbane River through Lockyer Creek that enters the Brisbane River just downstream of Wivenhoe Dam near Lowood. Another major tributary, the Bremer River, flows into the Brisbane River at Moggill. Wivenhoe Dam has no control over inflows into the Brisbane River from both these major tributaries.

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to minimise flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However, this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as additional inflows after this point would result in a dam failure. Similarly, there will be uncertainty on future rainfall that could occur which could not be releases if there was insufficient flood storage which could not be stored or released.

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.



2.2 Flood Operations

A real time flood monitoring and forecasting system has been established in the Wivenhoe and Somerset Dam catchments. This system employs radio telemetry to collect, transmit and receive rainfall and stream flow information. The system consists of around 230 field stations that automatically record rainfall and/or river heights at selected locations in the dam catchments. Most of these field stations are owned by Seqwater with the remainder belonging to other agencies.

The rainfall and river height data is transmitted to Seqwater's Flood Operations Centre in real time. Once received in the Flood Operations Centre, the data is processed using a Real Time Flood Model (RTFM) to estimate likely dam inflows and evaluate a range of possible inflow scenarios based on forecast and recorded rainfall in the dam catchments. The RTFM is a suite of hydrologic computer programs that utilise the real time data to assist in the operation of the dams during flood events.

Seqwater engineers use the RTFM for flood monitoring and forecasting during flood events to operate the dams in accordance with a Manual of Flood Mitigation (the origin of and objectives and procedures contained in the Manual of Flood Mitigation are explained in the following section of this document). Releases of water from the dams are optimised to minimise the impacts of flooding in accordance with the objectives and procedures contained in a Manual of Flood Mitigation.

The RTFM and data collection network performed well During the January 2011 event, with no failures experienced that compromised the ability of Seqwater to operate the dam.



3 MANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS

The Manual of Flood Mitigation for Wivenhoe and Somerset Dams, in its current form, was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

The primary objectives of the procedures contained in the flood manual are, in order of importance:

- · Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;
- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers primarily, this involves minimising inundation of the seven bridges below the dam upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.
- Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.



- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life. Under this strategy, the predicted water level is below 68.50 m AHD and the maximum release is 1,900m3/s.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD and the maximum release is less than 3,500m3/s.
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD but the maximum release is less than 4,000m3/s.
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.
 Under this strategy, the water level is predicted to exceed 74.0 m AHD and there is no limit to the maximum release. Consideration is given to managing flood releases to avoid fuse plug initiation if at all possible as this would compromise flood mitigation capacity in the short to medium term.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.



4 JANUARY 2011 FLOOD EVENT

4.1 Background

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML. The details of these events are as follows:

EVENT	EVENT START DATE	EVENT END DATE	VOLUME RELEASED (ML)
1	13/12/2010	16/12/2010	70,000
2	17/12/2010	24/12/2010	150,000
3	26/12/2010	02/01/2010	470,000

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.



JANUARY 2011 FLOOD			
S	tarting Level	Peak Height	Capacity
%	m AHD	m AHD	%
100	67.0	74.97	191
95	66.5	74.93	191
90	65.8	74.88	190
75	64.0	74.63	187
50	60.0	74.11	180

It should be noted that the possible reductions shown above are based up a unique dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

4.2 Event Decision Making

The following table contains a summary of the key decisions points associated with the current event. As at 16 January 2011, the event remains in progress.

DATE AND TIME	FLOOD EVENT MILESTONE	
07:00 06/01/2011	Rainfall is experienced in the dam catchments that will result in flood	
(Thursday)	releases, however Wivenhoe releases are delayed for 24 hours to allow	
	Lockyer Creek flood flows to pass downstream and prevent the isolation of	
	the community dependent of Burtons Bridge. The forecast is for 150mm	
	over the next 24 hours.	
15:00 07/01/2011	Wivenhoe releases commence, with operational strategy W1 in use.	
(Friday)	Rainfall for the next four days is estimated to be between 140mm and	
	300mm, with a forecast for rain easing on Tuesday 11 January 2011. All	
	bridges downstream of the dam with the exception of Fernvale Bridge and	
	Mt Crosby Weir Bridge are expected to be inundated for a number of days.	



06:00 09/01/2011 (Sunday)	Moderate to heavy rain periods forecast until Tuesday, but both Wivenhoe and Somerset dam levels were falling slowly, with Somerset at 1.27 m AHD above FSL and Wivenhoe 1.58 m AHD above FSL.
15:30 09/01/2011 (Sunday)	Following significant rain during the day a meeting of Duty Engineers is held. The QPF issued at 16:00 indicates 50mm to 80mm over the next 24 hours. Based on this forecast, it is anticipated that dam levels can be held to a maximum of 3.50 m AHD above FSL in Somerset and 5.5 m AHD above FSL in Wivenhoe. However, by 19:00 it was apparent that both Fernvale Bridge and Mt Crosby Weir Bridge would be inundated by the combined dam releases and Lockyer Creek flows and that the operational strategy had progressed to W2.
06:30 10/01/2011 (Monday)	Rainfall continued during the night and based on rainfall on the ground it was apparent the operational strategy had progressed to W3.
06:30 10/01/2011 (Monday)	Rainfall continued during the day but based on rainfall on the ground, operational strategy W3 remained in use. However it was apparent that any further heavy rain would result in progression of the operational strategy to W4.
08:00 11/01/2011 (Tuesday)	Rainfall continued during the night with isolated heavy falls in the Wivenhoe Dam catchment area and based on rainfall on the ground it was apparent the operational strategy would soon progress to W4 with Wivenhoe Dam exceeding 8.00 m AHD above FSL. The objective now was to limit outflows and subsequent flood damage to urban areas, while ensuring the structural safety of the dam.
11:00 11/01/2011 (Tuesday)	Rapid inflows were experienced in Wivenhoe Dam, with the dam rising almost a metre in eight hours. Releases were increased until the dam level stabilised in accordance with Strategy W4. Computer models were not reflecting actual dam inflows due to intense point rainfalls in the immediate catchment around the dam. Falls are estimated to be similar to those experienced at both Toowoomba and Upper Lockyer the previous day and are falling outside and between existing rain gauges.
21:00 11/01/2011 (Tuesday)	Wivenhoe Dam peaked. Peak release of 7450 cumecs with a level of 0.7 metres below fuse plug trigger.
22:00 11/01/2011	Wivenhoe Dam releases were closed off as quickly as possible over the



(Tuesday)	next 11 hours, while ensuring water levels in the dam did not rise further and initiate a fuse plug embankment.
08:00 12/01/2011 (Wednesday)	Minimum possible release level reached, with inflows matching outflows. Further reductions in release rate would likely cause the dam level to rise.
21:00 13/01/2011 (Thursday)	The 7 day dam drain down is commenced as Lockyer Creek and Bremer River peaks pass the Lower Brisbane area. Maximum release target is the limit of damaging floods in Brisbane being 3500 cumecs.
09:00 17/01/2011 (Monday)	Drain down continues, with released expected to cease on Wednesday 19 January 2011 unless further rainfall is experienced.




4.3 Flood Mitigation Benefits of Wivenhoe Dam

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam.

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.





JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



The strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area. This notion is supported by BOM.



5 EVENT REVIEW

Under the Manual of Operational Procedures for Flood Mitigation at Wivenhoe Dam and Somerset Dam that are approved and gazetted by the Department of Environment and Resource Management, there is a regulatory requirement that a report must be prepared as per the below wording:

"Seqwater must prepare a report after each Flood Event. The report must contain details of the procedures used, the reasons therefore and other pertinent information. Seqwater must forward the report to the Chief Executive within six weeks of the completion of the Flood Event."

Such a report was prepared for the flood events of February and March 2010 and copies are available. A copy of the Table of Contents of that report is included as Appendix 1. For this event, the report would be a comprehensive summary of all procedures, actions, outcomes and processes during the event.

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory requirements of the Act and the gazetted manual and any requirements of the Dam Safety Regulator. This would be done within 6 weeks of the closure of the current event as per the manual. This timeframe is subject to any new mobilisation of the Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies



- Review of factors impacting on the protection of urban areas
- Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices desirable to improve Seqwater's ability to manage events? For example, investigations to raise the dam to improve its flood storage capacity, If so, what are they and their implications.
 - Are changes to the facilities or work practices of other organisations desirable to improve Seqwater's abilities to manage these events? If so, what are they and their implications? (For example, would it be worth funding Brisbane River crossing upgrades so that floodwater could be released faster, while not adversely affecting access to properties—or maybe alternative strategies e.g. resupply operations could be put in place to achieve similar outcomes?)
 - Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert panel of
 review including representatives of DERM, Seqwater, BoM, affected Local Governments
 and other stakeholders as necessary.



Appendix A



FINAL REPORT – FLOOD EVENTS AT WIVENHOE, SOMERSET AND NORTH PINE DAMS FOR FEBRUARY AND MARCH 2010

TABLE OF CONTENTS

1.0 INTRODUCTION	1
2.0 FLOOD EVENT SUMMARY	2
2.1 FEBRUARY 2010	2
2.2 MARCH 2010	3
3.0 MOBILISATION AND STAFFING	5
3.1 16тн ТО 18тн FEBRUARY 2010	5
3.2 1sт TO 4тн MARCH	5
3.3 5тн ТО 6тн MARCH	5
3.4 6тн ТО 7тн MARCH	6
3.5 10тн ТО 11тн MARCH	6
4.0 EVENT RAINFALL	7
4.1 FEBRUARY 2010	7
4.2 MARCH 2010	9
5.0 INFLOW AND RELEASE DETAILS	12
5.1 16тн ТО 18тн FEBRUARY 2010	12
5.2 1sт MARCH 2010	15
5.3 6 / 7 _{TH} MARCH 2010	18
5.4 11тн MARCH 2010	21
6.0 DATA COLLECTION SYSTEM PERFORMANCE	25
6.1 NETWORK AVAILABILITY	25
6.2 RAINFALL	25
6.3 STREAM HEIGHT	26
6.3.1 Main Stream	26
6.3.2 Back-up Stream	
6.3.3 Headwater Sensors	
6.3.4 Sensor Calibration	
6.3.5 Stream Height Rating Curves	
7.0 DATA ANALYSIS PERFORMANCE	29
7.1 RUNOFF-ROUTING MODELS	29
7.2 BASEFLOW ASSESSMENT	29



8.0 COMMUNICATIONS	31
8.1 EVENT LOG	31
8.2 DECLARATION OF EVENT MOBILISATION	31
8.3 SHIFT HANDOVER	32
9.0 FLOOD MANAGEMENT STRATEGIES	33
9.1 16th TO 18th FEBRUARY 2010	
9.1.1 North Pine Dam	33
9.2 26th FEBRUARY TO 4th MARCH	35
9.2.1 Somerset and Wivenhoe Dam	35
9.2.2 North Pine Dam	38
9.3 4TH MARCH TO 7TH MARCH	41
9.3.1 North Pine Dam	41
9.4 10тн MARCH TO 11тн MARCH	44
9.4.1 North Pine Dam	44
10.0 RECOMMENDATIONS & CONCLUSIONS	46
10.1 DATA COLLECTION	46
10.2 DATA ANALYSIS	46
10.3 DIRECTIVES AND STATUS REPORTS	46
10.4 OPERATIONAL STRATEGIES	47
LIST OF APPENDICES	
APPENDIX A – FOC Attendance Logs & Event Logs	
APPENDIX B – Estimated Inflows and Release	
APPENDIX C – Reservoir Headwater Levels	
LIST OF TABLES	
Table 2.1: Storage Status Prior to February 2010 Event	2
Table 2.2: Dam Operations in March 2010	3
Table 4.1: February 2010 Sub-Catchment Rainfalls (mm)	7
Table 4.2: March 2010 Sub-Catchment Rainfalls (mm)	
Table 5.1: Peak Flood Level and Flows – 16th to 18th February 2010	
Table 5.2: Somerset Dam – 16th February to 20th February 2010	
Table 5.3: Wivenhoe Dam – 16th February to 20th February 2010	
· · · · · · · · · · · · · · · · · · ·	

Table 5.4: North Pine Dam – 16th February to 18th February 201014



Table 5.5: Peak Flood Level and Flows - 1st March 2010	15
Table 5.6: Somerset Dam - 24th February to 18th March 2010	17
Table 5.7: Wivenhoe Dam – 24th February to 18th March 2010	17
Table 5.8: North Pine Dam – 26th February to 4th March 2010	18
Table 5.9: Peak Flood Level and Flows – 6/7th March 2010	19
Table 5.10: North Pine Dam – 4th March to 6th March 2010	21
Table 5.11: Peak Flood Level and Flows – 11th March 2010	22
Table 5.12: North Pine Dam – 10տ March to 11տ March 2010	24
Table 9.1: North Pine Dam Gate Settings – 17th to 18th February 2010	35
Table 9.2: Somerset Dam gate Settings – 24th February 18th March	37
Table 9.3: North Pine Dam Gate Settings – 1st to 4th March 2010	39
Table 9.4: North Pine Dam Gate Settings – 5տ to 7տ March 2010	42
Table 9.5: North Pine Dam Gate Settings – 10th to 11th March 2010	45

Ministerial Briefing Note 17 January 2010 Flood Event January 2011

- 1. BACKGROUND INFORMATION ON WIVENHOE DAM
- 2. WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS
- 2.1 What were the benefits provided by Wivenhoe Dam during the current event?
- 2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
- 2.3 What is the role of the erodible fuse plug embankments?
- 2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?
- 2.5 Is there a detailed record of the events associated with the current flood?
- 3. THE MANUAL OF OPERATIONAL PROCEDURES FOR FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM
- 3.1 What is the Manual of Flood Mitigation and how was it developed?
- 3.2 What is contained in the Manual?
- 4. REGULATORY CONTEXT
- 5. COMPLIANCE WITH MANUAL
- 6. SEQWATER REPORT

1 BACKGROUND INFORMATION ON WIVENHOE DAM

Wivenhoe Dam was completed in 1984 and has two main functions;

- A 1,165,000 ML storage providing an urban water supply for Brisbane;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1,450,000 ML (this flood storage was increased in 2005 to 1,966,000 ML with the dam at the point of failure).

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam is scheduled to occur prior to 2035.

Wivenhoe Dam is in excellent condition with four Comprehensive Dam Safety reviews undertaken in the last 14 years, the latest in 2010.

2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 What were the benefits provided by Wivenhoe Dam during the current event?

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam. (Source: Flood Damage Tables provided to Seqwater by the Brisbane City Council).

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.


Depending on the nature of the event, the presence of Wivenhoe Dam could also potentially increase flood warning times to impacted areas. How these times may have been increased during the current event is presently difficult to quantify, but discussions will be held with BOM on this issue at a later date.

In addition, the strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area.

JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Brisbane City



JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to reduce flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as any additional inflows after this point would result in a dam failure. At any one time, there will always be uncertainty about what rain is going to occur. Hence, we cannot use all of the flood capacity as we would not be able to release sufficient water to cater for large inflows.

2.3 What is the role of the erodible fuse plug embankments?

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. The fuse plugs act as a safety valve to rapidly increase dam outflows if the structural safety of the dam is in danger. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.

2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML.

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.

JANUARY 2011 FLOOD			
Starting Level		Peak Height	Capacity
%	m AHD	m AHD	%
100	67.0	74.97	191
95	66.5	74.93	191
90	65.8	74.88	190
75	64.0	74.63	187
50	60.0	74.11	180

It should be noted that the possible reductions shown above are based up a unique dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

2.5 Is there a detailed record of the events associated with the current flood?

A preliminary report has been prepared and is attached to this briefing.

3 THE MANUAL OF FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM

3.1 What is the Manual of Flood Mitigation and how was it developed?

The Manual of Flood Mitigation for Wivenhoe and Somerset dams in its current form was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

3.2 What is contained in the Manual?

The primary objectives of the procedures contained in the Manual are, in order of importance:

- Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;
- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers
 primarily, this involves minimising inundation of the seven bridges below the dam
 upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.

 Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.

- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas.
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation.
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.

4 REGULATORY CONTEXT (Provided by Peter Allen and unedited)

These are contained in the Flood Mitigation Manual (manual) approved under sections 370 to 374 of the *Water Supply (Safety and Reliability) Act 2008*. The Chief Executive Officer (CEO) of DERM (or his delegate) approves the manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Act for the CEO to take into account when approving the manual.

The manual for the dams requires, amongst other matters:

- Flood operations to be conducted in accordance with manual's provisions. (There is an approval process specified in the manual, if Seqwater considers a different flood release strategy is desirable to deal with a particular flood event. This was not used in the January 2011 flood event)
- 2. Flood operations to be under the control of CEO-approved engineers (who are highly qualified and experienced)
- 3. Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- 4. Reporting on the flood operations during flood events.
- 5. Reviews after flood events such as the January 2011 event. For this flood event, the Queensland Government engaged Mr Brian Cooper, an independent consulting engineer, to review compliance with the manual. Mr Cooper concluded (Attachment??): "...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded..." (p.3 of the final report or other appropriate reference??)

The manual is separate from a draft communication protocol (Insert name) between the Local, State and Commonwealth government agencies that are affected by the dams' flood operations. This protocol is not binding on the parties to it is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Seqwater activates to manage such events. None of them are involved in any of the regulatory decisions concerning the dams or are members of the work unit (Office of the Water Supply Regulator) which undertakes the CEO's regulatory functions.

5	COMPLIANCE WITH THE MANUAL			
(To	(To be provided)			

6 SEQWATER REPORT

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory
 requirements of the Act and the gazetted manual and any requirements of the Dam
 Safety Regulator. This would be done within 6 weeks of the closure of the current
 event as per the manual. This timeframe is subject to any new mobilisation of the
 Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies
 - Review of factors impacting on the protection of urban areas
 - Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices
 desirable to improve Seqwater's ability to manage events? For
 example, investigations to raise the dam to improve its flood storage
 capacity, If so, what are they and their implications

- Are changes to the facilities or work practices of other organisations desirable to improve Seqwater's abilities to manage these events? If so, what are they and their implications? (For example, would it be worth funding Brisbane River crossing upgrades so that floodwater could be released faster, while not adversely affecting access to properties—or maybe alternative strategies e.g. resupply operations could be put in place to achieve similar outcomes?)
- Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert
 panel of review including representatives of DERM, Seqwater, BoM, affected Local
 Governments and other stakeholders as necessary.

Ministerial brief outline

What is the objective?

- a) Ensuring public transparency
- b) To answer the State's questions on the performance of Wivenhoe Dam operations
- c) Preparation for a public inquiry
- d) Normal and logical course of conduct after the occurrence of a major flood event Review requirement under the Flood Mitigation Manual

Background (focus on Brisbane River flooding issues)

- Design of Dam Storages/Spillway upgrade (Information provider: Seqwater and Peter Allen DERM) [1/3 to ½ a page]
- 2) "The Flood Event" Q&A (Information provider: Sequater) [2 ½ pages]
 - a. Chronology High level time step of events and significant decision making/changes

 more detailed time step information for Tuesday afternoon (i.e. what was the
 BOM forecast at the time, narrow peak etc.)
 - b. How does Wivenhoe Dam work as a flood mitigator?
 - c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?
 - d. Statistics on how much did Wivenhoe Dam knock off the flood peak.
 - e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?
 - f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?
 - g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)
 - h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
 - i. What is the fuse plug and why did it need to be maintained?
 - j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?
 - k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

- 3) The Flood Mitigation Manual (Information Provider: Seqwater/DERM) [1/2 to 1 page]
 - a. Describe the decision making framework Four strategies
 - b. How is the Manual designed to work?
 - c. History of Flood Mitigation Manual updates and peer review who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?
 - d. Attach Minister Robertson's request for advice on pre-emptive release and our response (*Information provider: SEQ Water Grid Manager*)
- 4) Regulatory context Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen DERM)
 - a. Flood Mitigation Manual approval
 - b. Formal reporting process under the Flood Mitigation Manual attach report resulting from the February 1999 flood event
 - c. Decision making process under the Flood Mitigation Manual
 - i. Who makes the flood release decisions under the Manual?
 - ii. who is informed/consulted?
 - iii. effect of the recent Flood Communication Protocol?
- 5) Brian Cooper Flood Mitigation Manual compliance review (*Responsible: SEQ Water Grid Manager*)

Seqwater report

(Information provider: Sequater, Peter Allen and Bob Reilly)

Seqwater, in consultation with Peter Allen and Bob Reilly, to set out how Seqwater's Flood Mitigation Manual Report to the Chief Executive on the effectiveness of the operational procedures will be undertaken.

- Attach table of contents of the 1999 Flood Mitigation Manual report
- Reflect Brian Cooper's compliance review
- Peer review establishment of an expert panel who will be on it? Peter Allen and Bob Reilly may provide some input.
- Communication Protocol and incorporation into the Flood Mitigation Manual (revisit in the next fortnight?)

Timeframes on the development of the report – consider urgency due to anticipated further rainfall during this summer.

Gina O'Driscoll

From:

Kathy Reilly [threereillys

Sent:

Sunday, 16 January 2011 6:00 PM

To:

Reilly Bob; phorrows

iohn bradlev

Barry Dennien,

Subject:

Dan Spiller, peter allen Re: Cabinet in co nfidence - Ministerial brief outline

Hi Peter

Peter Allen will provide you with some technical commentary, so I will concentrate on the wider issues. In the interests of time, I have not checked my comments with Peter Allen so he and your staff can feel to correct me if I have got my facts wrong.

Dam failure versus fuse plug activation

In the current event, the critical issue we were trying to avoid was activation of the fuse plugs, with the first one being activated at (I recall) 75.6 metres—not sure what this was in terms of percentage of capacity. As well as the adverse impacts of such activation cited in the text, the practical effect would also have been to increase, I understand, flood eights by about 0.5 metres in Brisbane. So, we had to avoid this outcome. (Also what the 0.5 metres been worth in rms of avoided property damage?)

Personally, I would emphasise more the arguments around what we had to do to avoid this outcome.

Reducing the peak flood in brisbane--last paragarph p.3

This is an important point. However the argument would be strengthened if you more comprehensively explained the reasoning behind the statement. For example, are we saying that because sequater reduced the flow from 6,000 cumecs to 2,500 cumecs, then this was the outcome, and that the only reason we could do that was because we were still 0.5 metres or so below fuse plug activation (and thus had a buffer if there was an unexpected surge in inflows?).

Also what is the 1 metre worth in terms of reduced property damage?

Section 2.4

Playing the devil's advocate for a moment with respect to the table on p.7, could someone convincingly argue that if the starting level had been 50% of FSL, you would have had the ability to reduce the releases from Wivenhoe below 2,500 cumecs at the height of the flood event, and thus further reduce the peak height in Brisbane /lpswich?

eqwater report (p.13)

The specific additional issues that I suggest we include are:

- whether it is worth investigating increasing the flood capacity of Wivenhoe--I know a fair bit of work has been
 done on this issue
- whether the Brisbane River crossings which act, under some situations as a constraint on the releases from Wivenhoe, should be replaced by bridges. For example if the smallest could pass, for example, 2,500 cumecs, then this could enable higher releases under some circumstances.
- Whether the policy of draining the flood compartment within 7 days should be modified.

I also suggest the review be undertaken by an independent expert and that an expert panel be formed to provide review of the report and identification of any additional issues requiring investigation—this is important if you are picking up possibel improvement by otehr agencies.

Minor points.

- throughout the text can we be clear what we mean by the term "failure"—to the Minister I suspect this means
 the dam will collapse and I do not think this is what meant in some cases.
- the spillway upgrade in 2035 is not intended to improve flood mitgation capacity, I understand (p.2)

1

- the first few paragraphs in section 2.1 refer to the sceanrio where Wivenhoe did not exist--could this be made clearer in the text?
- Finally, could we make the point that Wivenhoe/Somerset does not control Lockyer/Bremer and that the flood flow at the river peak was compromised of x % from these sources. In the last few days, I have explained to many people around Milton/Auchenflower (where there was significant flooding) this point and they are always surprised. There appears to be a strong view in the community that Wivenhoe was supposed to stop any repetition of the 1974 flood and therefore it "failed" in this task given what has happened.

egards

.)h

---- Original Message ----

From: Reilly Bob

To: threereillys

Sent: Sunday, January 16, 2011 4:33 PM

Subject: Fw: Cabinet in co nfidence - Ministerial brief outline

---- Original Message ----

From: Peter Borrows <pborrows

To: Reilly Bob; Rob Drury <rdrury

>; Duty Seq <<u>dutyseq</u>

r: Bradley John; Dennien Barry

; spiller daniel Ce: Lyons Michael

; Mike Foster <<u>infoster</u>

>; Elaina Smouha <elainamii

Allen

Data:

Sent: Sun Jan 16 16:28:29 2011

Subject: Cabinet in confidence - Ministerial brief outline

Please see attached draft with attachment.

relation to the draft contents outline sent yesterday, the following is a cross reference FYI.

The attached Ministerial Briefing Note addresses the questions contained in the Ministerial Information Request as follows:

1) Design of Dam - Storages/Spillway upgrade

Refer Section 1

- 2) "The Flood Event" Q&A
- a. Chronology High level time step of events and significant decision making/changes more detailed time step information for Tuesday afternoon (i.e. what was the BOM forecast at the time, narrow peak etc.)

Refer Section 2.5

b. How does Wivenhoe Dam work as a flood mitigator?

2

Refer Sections 2.1, 2.3 and 3.1

c. What are the factors being balanced when making decisions about the amount of dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?

Refer Sections 3.1 and 3.2

Statistics on how much did Wivenhoe Dam knock off the flood peak.

Refer Section 2.1

e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?

Refer Sections 2.1 and 2.2

f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?

Refer Section 2.4

If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)

Refer Section 2.4

h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Refer Section 2.2

i. What is the fuse plug and why did it need to be maintained?

Refer Section 2.3

j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?

Refer Section 2.4

k. Did Sequater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

Refer Section 2.4

3) The Flood Mitigation Manual

Refer Section 3.1

a. Describe the decision making framework - Four strategies

Refer Section 3.2

b. How is the Manual designed to work?

Refer Section 3.2

c. History of Flood Mitigation Manual updates and peer review – who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?

Refer Section 3.1

4) Regulatory context - Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen - DERM)

Refer Section 4

3

Regards, Peter.

Peter Borrows

Chief Executive Officer

Queensland Bulk Water Supply Authority trading as Sequater

E pborrows

Level 3, 240 Margaret St. Brisbane City QLD 4000 PO Box 16146, City East QLD 4002

Website | www.seqwater.com.au < http://www.seqwater.com.au/>

From: Elaina Smouha [mailto:elainamin

Sent: Saturday, 15 January 2011 5:03 PM

To: Mike Foster; peter allen

; Peter Borrows; Rob Drury; Duty Seq

daniel.spiller

Sc: john.bradley

barry.dennien

Elaina Smouha

michael.lyons Subject: Cabinet in confidence - Ministerial brief outline

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance

SEQ Water Grid Manager

Email: elaina.smouha

<mailto:claina.smoulia

Visit: Level 15, 53 Albert Street Brisbane

Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

----Safe Stamp-

Your Anti-virus Service scanned this email. It is safe from known viruses.

For more information regarding this service, please contact your service provider.

Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Sequater).

Think B4U Print

1 ream of paper = 6% of a tree and 5.4kg CO2 in the atmosphere

3 sheets of A4 paper = 1 litre of water

From:

Elaina Smouha <elainamir

Sent:

Sunday, January 16, 2011 6:05 PM

To:

Peter Borrows <pborrows

Cc:

Barry Dennien <Barry Dennien

<Daniel.Spiller

Subject:

Re: Cabinet in co nfidence - Ministerial brief outline

Attach:

Seqwater Jan_2011_Flood_Event_Ver_1_draft_for_distribution[1].docx; Seqwater

Ministerial Briefing Note January 17 2011 Final Draft for distribution[1].docx

>; Dan Spiller

Peter

As per your conversation with Barry, we have highlighted some queries within your attached reports.

Regards

Elaina

On Sun, Jan 16, 2011 at 4:28 PM, Peter Borrows pborrows

> wrote:

Please see attached draft with attachment.

In relation to the draft contents outline sent yesterday, the following is a cross reference FYI.

The attached Ministerial Briefing Note addresses the questions contained in the Ministerial Information Request as follows:

1) Design of Dam - Storages/Spillway upgrade

Refer Section 1

- 2) "The Flood Event" Q&A
 - a. Chronology High level time step of events and significant decision making/changes more detailed time step information for Tuesday afternoon (i.e. what was the BOM forecast at the time, narrow peak etc.)

Refer Section 2.5

b. How does Wivenhoe Dam work as a flood mitigator?

Refer Sections 2.1, 2.3 and 3.1

c. What are the factors being balanced when making decisions about the amount of

dam releases? To what extent does information from the Bureau of Meteorology/rain gauges influence decisions? How reliable is this information?

Refer Sections 3.1 and 3.2

d. Statistics on how much did Wivenhoe Dam knock off the flood peak.

Refer Section 2.1

e. What would have happened if Wivenhoe Dam had not been built and we only had Somerset Dam? What damage would have been caused compared to what has currently been experienced (damage statistics)?

Refer Sections 2.1 and 2.2

f. If we have undertaken pre-emptive dam releases to bring Wivenhoe Dam's full supply level down to lower than what we had maintained (i.e. 60%), what would have been the river height for the period that this flood event occurred?

Refer Section 2.4

g. If pre-emptive dam releases would not have made a difference, why? (i.e. why did we not release earlier?)

Refer Section 2.4

h. Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Refer Section 2.2

i. What is the fuse plug and why did it need to be maintained?

Refer Section 2.3

j. What damage or town isolation occurred during the Wivenhoe Dam releases that occurred since October 2010?

Refer Section 2.4

k. Did Seqwater have time to reduce the dam level between the 5 events? If so, would it have made a difference to this flood event?

Refer Section 2.4

3) The Flood Mitigation Manual

Refer Section 3.1

a. Describe the decision making framework - Four strategies

Refer Section 3.2

b. How is the Manual designed to work?

Refer Section 3.2

c. History of Flood Mitigation Manual updates and peer review – who was on the panels, studies that fed into previous versions of the Manual and who was involved in these studies?

Refer Section 3.1

4) Regulatory context - Water Supply (Safety and Reliability) Act 2008 (Information provider: Peter Allen - DERM)

Refer Section 4

Regards, Peter.

Peter Borrows

Chief Executive Officer

Queensland Bulk Water Supply Authority trading as Seqwater

cid:image003.png@01CB0654.C3

Е рьопомя

Level 3, 240 Margaret St, Brisbane City QLD 4000 PO Box 16146, City East QLD 4002

Website | www.segwater.com.au

cid:image008.png@01CB8736.F84905B0

From: Elaina Smouha [mailto:elainamir Sent: Saturday, 15 January 2011 5:03 PM To: Mike Foster; peter aller

Cc: john bradlev

barry.dennien

jelaina Smouha

jelaina Smouha

Subject: Cabinet in confidence - Ministerial brief outline

Dear All

To assist, attached is a Ministerial brief outline as per our recent teleconference, for Monday's Emergency Cabinet meeting. It also records those who will be providing information for the Background and Flood Mitigation Manual report process.

As discussed, the brief needs to be provided to Minister Robertson tomorrow (Sunday, 16 January 2011).

Regards

Elaina

Elaina Smouha

Director, Governance and Regulatory Compliance

SEQ Water Grid Manager

Email: elaina.smouha

Visit: Level 15, 53 Albert Street Brisbane

Post: PO Box 16205, City East QLD 4002

ABN: 14783 317 630

Your Anti-virus Service scanned this email. It is safe from known viruses.

For more information regarding this service, please contact your service provider.

Important information: This email and any attached information is intended only for the addressee and may contain confidential and/or privileged information. If you are not the addressee, you are notified that any transmission, distribution, or other use of this information is strictly prohibited. The

confidentiality attached to this email is not waived, lost or destroyed by reasons of mistaken delivery to you. If you have received this email in error please contact the sender immediately and delete the material from your email system. QLD Bulk Water Supply Authority ABN75450239876 (Trading as Seqwater).



JANUARY 2011 FLOOD EVENT



TABLE OF CONTENTS

1	IN.	TRODUCTION	1
2	WI	VENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS	2
	2.1	Flood Mitigation	2
	2.2	Flood Operations	3
3	MA	ANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS	4
4	JA	NUARY 2011 FLOOD EVENT	6
	4.1	Background	6
	4.2	Event Decision Making	7
	4.3	Flood Mitigation Benefits of Wivenhoe Dam	11
5	EV	/ENT REVIEW	13



1 INTRODUCTION

Wivenhoe Dam was constructed by the Queensland Government between 1977 and 1984. The dam is a 56 m AHD high and 2.3 kilometre long earth and rock embankment separated into two parts by a concrete gravity spillway. The spillway is controlled by 5 radial gates, each 12.0 metres wide by 16.0 m AHD high. Two saddle dam embankments are located on the left side of the reservoir.

The dam spillway capacity was upgraded in 2005. This was done primarily through the construction of a 164 metre wide secondary spillway through the right abutment of the existing dam. This spillway contains three erodible earth fill fuse plug embankments that are initiated at different dam levels in excess of EL 75.6.

The dam has two main functions by providing:

- A 1,165,000 ML storage at full supply level (FSL EL 67.0) providing an urban water supply for Brisbane and surrounding areas;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1,450,000 ML up to EL77 (this flood level was increased as part the 2005 upgrade to allow a water level of EL80m and a temporary flood storage volume of 1,966,000 ML with all fuse plugs initiated and the dam at the point of failure).

The dam has an EXTREME hazard classification under ANCOLD guidelines because of the significant development downstream in the Brisbane and Ipswich metropolitan areas, with the population at risk in the event of a dam failure numbering in the hundreds of thousands.

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam is scheduled to occur prior to 2035 to enable the dam to safely pass the Probable Maximum Flood. This work will involve the reconstruction of Saddle Dam 2 as a fuse plug spillway.

Wivenhoe Dam is in excellent condition. Comprehensive Dam Safety reviews undertaken in accordance with ANCOLD guidelines have been undertaken in 1997 (Gutteridge, Haskins & Davey Pty Ltd), 2003 (Wivenhoe Alliance), 2006 (NSW Department of Commerce), 2009 (GHD) and September 2010 (Seqwater). The reports concluded that the design of the dam is in accordance with modern day standards and that there are no significant outstanding design or construction issues that require investigation.



2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 Flood Mitigation

The Brisbane River catchment covers an area of approximately 14,000 square kilometres of which about half is below Wivenhoe Dam. Maximum overall flood mitigation effect is achieved by operating Wivenhoe Dam in conjunction with Somerset Dam. Although Somerset and Wivenhoe Dam reduce flooding in Brisbane City, major flooding can still occur. The Lockyer-Laidley Valley drains into the Brisbane River through Lockyer Creek that enters the Brisbane River just downstream of Wivenhoe Dam near Lowood. Another major tributary, the Bremer River, flows into the Brisbane River at Moggill. Wivenhoe Dam has no control over inflows into the Brisbane River from both these major tributaries.

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to minimise flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However, this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as additional inflows after this point would result in a dam failure. Similarly, there will be uncertainty on future rainfall that could occur which could not be releases if there was insufficient flood storage which could not be stored or released.

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.



2.2 Flood Operations

A real time flood monitoring and forecasting system has been established in the Wivenhoe and Somerset Dam catchments. This system employs radio telemetry to collect, transmit and receive rainfall and stream flow information. The system consists of around 230 field stations that automatically record rainfall and/or river heights at selected locations in the dam catchments. Most of these field stations are owned by Seqwater with the remainder belonging to other agencies.

The rainfall and river height data is transmitted to Seqwater's Flood Operations Centre in real time. Once received in the Flood Operations Centre, the data is processed using a Real Time Flood Model (RTFM) to estimate likely dam inflows and evaluate a range of possible inflow scenarios based on forecast and recorded rainfall in the dam catchments. The RTFM is a suite of hydrologic computer programs that utilise the real time data to assist in the operation of the dams during flood events.

Seqwater engineers use the RTFM for flood monitoring and forecasting during flood events to operate the dams in accordance with a Manual of Flood Mitigation (the origin of and objectives and procedures contained in the Manual of Flood Mitigation are explained in the following section of this document). Releases of water from the dams are optimised to minimise the impacts of flooding in accordance with the objectives and procedures contained in a Manual of Flood Mitigation.

The RTFM and data collection network performed well During the January 2011 event, with no failures experienced that compromised the ability of Seqwater to operate the dam. Inconsistent with statement on page 8?



3 MANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS

The Manual of Flood Mitigation for Wivenhoe and Somerset Dams, in its current form, was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

The primary objectives of the procedures contained in the flood manual are, in order of importance:

- Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;
- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers primarily, this involves minimising inundation of the seven bridges below the dam upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.
- Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.



- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life. Under this strategy, the predicted water level is below 68.50 m AHD and the maximum release is 1,900m3/s.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD and the maximum release is less than 3,500m3/s. River flows at Moggill? Not releases?
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD but the maximum release is less than 4,000m3/s. River flows at Moggill? Not releases?
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.
 Under this strategy, the water level is predicted to exceed 74.0 m AHD and there is no limit
 to the maximum release. Consideration is given to managing flood releases to avoid fuse
 plug initiation if at all possible as this would compromise flood mitigation capacity in the
 short to medium term.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.



4 JANUARY 2011 FLOOD EVENT

4.1 Background

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML. The details of these events are as follows:

EVENT	EVENT START DATE	EVENT END DATE	VOLUME RELEASED (ML)
1	13/12/2010	16/12/2010	70,000
2	17/12/2010	24/12/2010	150,000 Should this be 370,000 as per teleconference?
3	26/12/2010	02/01/2010	470,000

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This



is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.

	JANUARY 2011 FLOOD			
Starting Level		Peak Height	Capacity	
%	m AHD	m AHD	%	
100	67.0	74.97	191	
95	66.5	74.93	191	
90	65.8	74.88	190	
75	64.0	74.63	187	
50	60.0	74.11	180	

It should be noted that the possible reductions shown above are based up a unique dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

Assumptions for model?

Is it a dual or triple peak? Should we explain in detail why is it so unique?

4.2 Event Decision Making

The following table contains a summary of the key decisions points associated with the current event. As at 16 January 2011, the event remains in progress.

Weather forecasts were consistently less than actual. Emphasise reliance on BOM advice.

Need to specify BOM forecasts and actual rainfall experienced for each time step.

DATE AND TIME	FLOOD EVENT MILESTONE
07:00 06/01/2011 (Thursday)	Rainfall is experienced in the dam catchments that will result in flood releases, however Wivenhoe releases are delayed for 24 hours to allow
(maioday)	Lockyer Creek flood flows to pass downstream and prevent the isolation of the community dependent of Burtons Bridge. The forecast is for 150mm over the next 24 hours.
15:00 07/01/2011 (Friday)	Wivenhoe releases commence, with operational strategy W1 in use. Rainfall for the next four days is estimated to be between 140mm and 300mm, with a forecast for rain easing on Tuesday 11 January 2011. All bridges downstream of the dam with the exception of Fernvale Bridge and



Mt Crosby Weir Bridge are expected to be inundated for a number of days.



06:00 09/01/2011 (Sunday)	Moderate to heavy rain periods forecast until Tuesday, but both Wivenhoe and Somerset dam levels were falling slowly, with Somerset at 1.27 m AHD above FSL and Wivenhoe 1.58 m AHD above FSL.
15:30 09/01/2011 (Sunday)	Following significant rain during the day a meeting of Duty Engineers is held. The QPF issued at 16:00 indicates 50mm to 80mm over the next 24 hours. Based on this forecast, it is anticipated that dam levels can be held to a maximum of 3.50 m AHD above FSL in Somerset and 5.5 m AHD above FSL in Wivenhoe. However, by 19:00 it was apparent that both Fernvale Bridge and Mt Crosby Weir Bridge would be inundated by the combined dam releases and Lockyer Creek flows and that the operational strategy had progressed to W2.
06:30 10/01/2011 (Monday)	Rainfall continued during the night and based on rainfall on the ground it was apparent the operational strategy had progressed to W3.
06:30 10/01/2011 (Monday)	Rainfall continued during the day but based on rainfall on the ground, operational strategy W3 remained in use. However it was apparent that any further heavy rain would result in progression of the operational strategy to W4.
08:00 11/01/2011 (Tuesday)	Rainfall continued during the night with isolated heavy falls in the Wivenhoe Dam catchment area and based on rainfall on the ground it was apparent the operational strategy would soon progress to W4 with Wivenhoe Dam exceeding 8.00 m AHD above FSL. The objective now was to limit outflows and subsequent flood damage to urban areas, while ensuring the structural safety of the dam.
11:00 11/01/2011 (Tuesday)	Rapid inflows were experienced in Wivenhoe Dam, with the dam rising almost a metre in eight hours. Releases were increased until the dam level stabilised in accordance with Strategy W4. Computer models were not reflecting actual dam inflows due to intense point rainfalls in the immediate catchment around the dam. Falls are estimated to be similar to those experienced at both Toowoomba and Upper Lockyer the previous day and are falling outside and between existing rain gauges.
21:00 11/01/2011 (Tuesday)	Wivenhoe Dam peaked. Peak release of 7450 cumecs with a level of 0.7 metres below fuse plug trigger.
22:00 11/01/2011	Wivenhoe Dam releases were closed off as quickly as possible over the



(Tuesday)	next 11 hours, while ensuring water levels in the dam did not rise further and initiate a fuse plug embankment.
08:00 12/01/2011 (Wednesday)	Minimum possible release level reached, with inflows matching outflows. Further reductions in release rate would likely cause the dam level to rise.
21:00 13/01/2011 (Thursday)	The 7 day dam drain down is commenced as Lockyer Creek and Bremer River peaks pass the Lower Brisbane area. Maximum release target is the limit of damaging floods in Brisbane being 3500 cumecs.
09:00 17/01/2011 (Monday)	Drain down continues, with released expected to cease on Wednesday 19 January 2011 unless further rainfall is experienced.




4.3 Flood Mitigation Benefits of Wivenhoe Dam

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam.

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.





JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



The strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area. This notion is supported by BOM.

Blue line of graph — Breakdown the component of % of Wivenhoe Dam release and downstream inflows.



5 EVENT REVIEW

Under the Manual of Operational Procedures for Flood Mitigation at Wivenhoe Dam and Somerset Dam that are approved and gazetted by the Department of Environment and Resource Management, there is a regulatory requirement that a report must be prepared as per the below wording:

"Seqwater must prepare a report after each Flood Event. The report must contain details of the procedures used, the reasons therefore and other pertinent information. Seqwater must forward the report to the Chief Executive within six weeks of the completion of the Flood Event."

Such a report was prepared for the flood events of February and March 2010 and copies are available. A copy of the Table of Contents of that report is included as Appendix 1. For this event, the report would be a comprehensive summary of all procedures, actions, outcomes and processes during the event.

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory requirements of the Act and the gazetted manual and any requirements of the Dam Safety Regulator. This would be done within 6 weeks of the closure of the current event as per the manual. This timeframe is subject to any new mobilisation of the Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies



- Review of factors impacting on the protection of urban areas
- Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices desirable to improve Seqwater's ability to manage events? For example, investigations to raise the dam to improve its flood storage capacity, If so, what are they and their implications.
 - Are changes to the facilities or work practices of other organisations desirable to improve Seqwater's abilities to manage these events? If so, what are they and their implications? (For example, would it be worth funding Brisbane River crossing upgrades so that floodwater could be released faster, while not adversely affecting access to properties--or maybe alternative strategies e.g. resupply operations could be put in place to achieve similar outcomes?)
 - Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert panel of
 review including representatives of DERM, Seqwater, BoM, affected Local Governments
 and other stakeholders as necessary.



Appendix A



FINAL REPORT – FLOOD EVENTS AT WIVENHOE, SOMERSET AND NORTH PINE DAMS FOR FEBRUARY AND MARCH 2010

TABLE OF CONTENTS

1.0 INTRODUCTION	. 1
2.0 FLOOD EVENT SUMMARY	2
2.1 FEBRUARY 2010	. 2
2.2 MARCH 2010	3
3.0 MOBILISATION AND STAFFING	5
3.1 16тн ТО 18тн FEBRUARY 2010	.5
3.2 1sт TO 4тн MARCH	5
3.3 5тн ТО 6тн MARCH	.5
3.4 6тн ТО 7тн MARCH	6
3.5 10тн ТО 11тн MARCH	6
4.0 EVENT RAINFALL	7
4.1 FEBRUARY 2010	.7
4.2 MARCH 2010	9
5.0 INFLOW AND RELEASE DETAILS	.12
5.1 16тн ТО 18тн FEBRUARY 2010	.12
5.2 1st MARCH 2010	.15
5.3 6 / 7тн MARCH 2010	.18
5.4 11тн MARCH 2010	.21
6.0 DATA COLLECTION SYSTEM PERFORMANCE	.25
6.1 NETWORK AVAILABILITY	.25
6.2 RAINFALL	.25
6.3 STREAM HEIGHT	.26
6.3.1 Main Stream	. 26
6.3.2 Back-up Stream	. 27
6.3.3 Headwater Sensors	
6.3.4 Sensor Calibration.	
6.3.5 Stream Height Rating Curves	
7.0 DATA ANALYSIS PERFORMANCE	
7.1 RUNOFF-ROUTING MODELS	
7.2 BASEFLOW ASSESSMENT	.29



8.0 COMMUNICATIONS	31
8.1 EVENT LOG	31
8.2 DECLARATION OF EVENT MOBILISATION	31
8.3 SHIFT HANDOVER	32
9.0 FLOOD MANAGEMENT STRATEGIES	33
9.1 16тн TO 18тн FEBRUARY 2010	33
9.1.1 North Pine Dam	
9.2 26TH FEBRUARY TO 4TH MARCH	35
9.2.1 Somerset and Wivenhoe Dam	35
9.2.2 North Pine Dam	38
9.3 4th MARCH TO 7th MARCH	41
9.3.1 North Pine Dam	41
9.4 10тн MARCH TO 11тн MARCH	44
9.4.1 North Pine Dam	44
10.0 RECOMMENDATIONS & CONCLUSIONS	46
10.1 DATA COLLECTION	46
10.2 DATA ANALYSIS	46
10.3 DIRECTIVES AND STATUS REPORTS	46
10.4 OPERATIONAL STRATEGIES	47

LIST OF APPENDICES

APPENDIX A - FOC Attendance Logs & Event Logs

APPENDIX B - Estimated Inflows and Release

APPENDIX C - Reservoir Headwater Levels

LIST OF TABLES

Table 2.1: Storage Status Prior to February 2010 Event	.2
Table 2.2: Dam Operations in March 2010	.3
Table 4.1: February 2010 Sub-Catchment Rainfalls (mm)	.7
Table 4.2: March 2010 Sub-Catchment Rainfalls (mm)	.9
Table 5.1: Peak Flood Level and Flows - 16th to 18th February 2010	.12
Table 5.2: Somerset Dam - 16th February to 20th February 2010	.14
Table 5.3: Wivenhoe Dam – 16th February to 20th February 2010	.14
Table 5.4: North Pine Dam – 16th February to 18th February 2010	.14



Table 5.5: Peak Flood Level and Flows – 1st March 2010	15
Table 5.6: Somerset Dam – 24th February to 18th March 2010	17
Table 5.7: Wivenhoe Dam – 24th February to 18th March 2010	17
Table 5.8: North Pine Dam - 26th February to 4th March 2010	18
Table 5.9: Peak Flood Level and Flows - 6/7th March 2010	19
Table 5.10: North Pine Dam - 4th March to 6th March 2010	21
Table 5.11: Peak Flood Level and Flows - 11th March 2010	22
Table 5.12: North Pine Dam – 10th March to 11th March 2010	24
Table 9.1: North Pine Dam Gate Settings - 17th to 18th February 2010	35
Table 9.2: Somerset Dam gate Settings – 24th February 18th March	37
Table 9.3: North Pine Dam Gate Settings – 1st to 4th March 2010	39
Table 9.4: North Pine Dam Gate Settings – 5th to 7th March 2010	42
Table 9.5: North Pine Dam Gate Settings - 10th to 11th March 2010	45

Ministerial Briefing Note 17 January 2010 Flood Event January 2011

1. BACKGROUND INFORMATION ON WIVENHOE DAM

2.	WIVENHOE DAM FL	OOD MITIGATION	AND FLOOD	OPERATIONS

- 2.1 What were the benefits provided by Wivenhoe Dam during the current event?
- 2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
- 2.3 What is the role of the erodible fuse plug embankments?
- 2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?
- 2.5 Is there a detailed record of the events associated with the current flood?

3. THE MANUAL OF OPERATIONAL PROCEDURES FOR FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM

- 3.1 What is the Manual of Flood Mitigation and how was it developed?
- 3.2 What is contained in the Manual?
- 4. REGULATORY CONTEXT
- 5. COMPLIANCE WITH MANUAL
- 6. SEQWATER REPORT

1 BACKGROUND INFORMATION ON WIVENHOE DAM

Wivenhoe Dam was completed in 1984 and has two main functions;

- A 1,165,000 ML storage providing an urban water supply for Brisbane;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1,450,000 ML (this flood storage was increased in 2005 to 1,966,000 ML with the dam at the point of failure).

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam is scheduled to occur prior to 2035. Would it have made any difference to the current flood event?

Was it relevant to this event i.e any di? Would water have been released through it? Would the Flood Mitigation Manual decision levels changed?

Wivenhoe Dam is in excellent condition with four Comprehensive Dam Safety reviews undertaken in the last 14 years, the latest in 2010.

2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 What were the benefits provided by Wivenhoe Dam during the current event?

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam. (Source: Flood Damage Tables provided to Seqwater by the Brisbane City Council).

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.


Depending on the nature of the event, the presence of Wivenhoe Dam could also potentially increase flood warning times to impacted areas. How these times may have been increased during the current event is presently difficult to quantify, but discussions will be held with BOM on this issue at a later date.

In addition, the strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area.

JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Brisbane City



JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



Blue line of graph – Breakdown the component of % of Wivenhoe Dam release and downstream inflows:

4 | Page

2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to reduce flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as any additional inflows after this point would result in a dam failure. At any one time, there will always be uncertainty about what rain is going to occur. Hence, we cannot use all of the flood capacity as we would not be able to release sufficient water to cater for large inflows.

Why didn't we let the first fuse plug go? Why not 200%? Why not 205%? Dam is rock core etc.

2.3 What is the role of the erodible fuse plug embankments?

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. The fuse plugs act as a safety valve to rapidly increase dam outflows if the structural safety of the dam is in danger. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.

2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML.

Detail specific impacts — which bridges knocked out, how long people isolated, which towns impacted, how many people impacted?

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.

What are the assumptions in terms of the releases at different levels?

7 | Page

		JANUARY 2011 FLOOD	
Starting Level		Peak Height	Capacity
%	m AHD	m AHD	%
100	67.0	74.97	191
95	66.5	74.93	191
90	65.8	74.88	190
75	64.0	74.63	187
50	60.0	74.11	180

It should be noted that the possible reductions shown above are based up a unique dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

2.5 Is there a detailed record of the events associated with the current flood?

A preliminary report has been prepared and is attached to this briefing.

3 THE MANUAL OF FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM

3.1 What is the Manual of Flood Mitigation and how was it developed?

The Manual of Flood Mitigation for Wivenhoe and Somerset dams in its current form was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

Can we attach CV of experts? Note Colin Apelt chaired the Brisbane Flood Study and chairs the current Brisbane Flood taskforce.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

3.2 What is contained in the Manual?

The primary objectives of the procedures contained in the Manual are, in order of importance:

- Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;

9 | Page

- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers primarily, this involves minimising inundation of the seven bridges below the dam upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.
- Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.

- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas.
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation.
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.

4 REGULATORY CONTEXT (Provided by Peter Allen and unedited)

These are contained in the Flood Mitigation Manual (manual) approved under sections 370 to 374 of the *Water Supply (Safety and Reliability) Act 2008*. The Chief Executive Officer (CEO) of DERM (or his delegate) approves the manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Act for the CEO to take into account when approving the manual.

The manual for the dams requires, amongst other matters:

- Flood operations to be conducted in accordance with manual's provisions. (There is an approval process specified in the manual, if Seqwater considers a different flood release strategy is desirable to deal with a particular flood event. This was not used in the January 2011 flood event)
- 2. Flood operations to be under the control of CEO-approved engineers (who are highly qualified and experienced)
- 3. Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- 4. Reporting on the flood operations during flood events.
- 5. Reviews after flood events such as the January 2011 event. For this flood event, the Queensland Government engaged Mr Brian Cooper, an independent consulting engineer, to review compliance with the manual. Mr Cooper concluded (Attachment??): "...The strategies in the Flood Mitigation Manual have been followed, allowing for the discretion given to make variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to these responsible for flood operations and the way events unfolded..." (p.3 of the final report or other appropriate reference??)

The manual is separate from a draft communication protocol (Insert name) between the Local, State and Commonwealth government agencies that are affected by the dams' flood operations. This protocol is not binding on the parties to it is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Sequater activates to manage such events. None of them are involved in any of the regulatory decisions concerning the dams or are members of the work unit (Office of the Water Supply Regulator) which undertakes the CEO's regulatory functions.

5 COMPLIANCE WITH THE MANUAL

(To be provided)

6 SEQWATER REPORT

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory requirements of the Act and the gazetted manual and any requirements of the Dam Safety Regulator. This would be done within 6 weeks of the closure of the current event as per the manual. This timeframe is subject to any new mobilisation of the Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies
 - Review of factors impacting on the protection of urban areas
 - Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices
 desirable to improve Seqwater's ability to manage events? For
 example, investigations to raise the dam to improve its flood storage
 capacity, If so, what are they and their implications

14 | Page

- Are changes to the facilities or work practices of other organisations desirable to improve Seqwater's abilities to manage these events? If so, what are they and their implications? (For example, would it be worth funding Brisbane River crossing upgrades so that floodwater could be released faster, while not adversely affecting access to properties--or maybe alternative strategies e.g. resupply operations could be put in place to achieve similar outcomes?)
- Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert
 panel of review including representatives of DERM, Seqwater, BoM, affected Local
 Governments and other stakeholders as necessary.

Suzie Emery

From:

Barry Dennien [Barry.Dennien

Sent:

Sunday, 16 January 2011 7:36 PM

To:

Dan Spiller

Subject:

Fwd: River height calculation [SEC=UNCLASSIFIED]

Regards Barry Dennien

Begin forwarded message:

From: Peter Baddiley < P.Baddiley

Date: 16 January 2011 7:05:22 PM AEST

To: Barry Dennien < Barry. Dennien

Cc: Rob Vertessy < R. Vertessy , Peter Baddiley < P. Baddiley

Subject: RE: River height calculation [SEC=UNCLASSIFIED]

Thanks Barry for your kind remark. It is a testing time for all of us.

Re your request, I think the Bureau need to respond to this request because it relates to questions about predicted flood levels which is a Bureau responsibility.

From what I can see now with the data that the Bureau has and from my involvement in the events on Tuesday/Wednesday, the significant increase in WD discharges through Tuesday clearly has a significant impact (increase) on downstream peak flood levels, rates of rise and timing.

However, again from my understanding of what happened based on operational data, modelling and the warning and predicting operations through Tue/Wed, the dam operators firstly increased the releases to manage the dam level and its safety (by necessity of course because of the intense Tuesday rainfalls); but then, when the dam was at a high level, very quickly moved to rapidly reducing the releases to minimise or mitigate the downstream flooding.

I believe, again from what I have before me, that this decision did reduce levels from what they otherwise would have been if a more conservative operation had applied. I don't have experience in operating dams, but it seemed to me a very solid, but "big" decision to make in the timeframe it seems to have been made (again from the reduced discharges evident during Wed morning).

All of thes initial viewpoints, of course, needs to be tested with more detailed assessment and modelling yet to happen.

regards, peter

Peter Baddiley
Regional Hydrology Manager
Climate & Water Division
Bureau of Meteorology
Level 21, 69 Ann Street
GPO Box 413, BRISBANE, QLD, AUSTRALIA 4001

EMAIL: p.baddiley

EMAIL for flood matters: flood.qld

WWW: www.bom.gov.au

From: Barry Dennien [mailto:Barry.Dennien Sent: Sunday, 16 January 2011 1:17 PM

To: Peter Baddiley

Subject: River height calculation

Hi Peter

You and your team are doing a great job.

We are getting many requests for stats on Wivenhoe's performance during the flood event.

One stat that would be useful to hold back the media until all info is collated is how much impact on river levels did the peak release on Tuesday night have on the river (tuesday noon to midnight), I understand not much however an estimate at this stage would be good.

Regards

Barry

This email, together with any attachments, is intended for the named recipient(s) only; and may contain privileged and confidential information. You understand that any privilege or confidentiality attached to this message is not waived, lost or destroyed because you have received this message in error. If received in error, you are asked to inform the sender as quickly as possible and delete this email and any copies of this from your computer system network.

If not an intended recipient of this email, you must not copy, distribute or take any action(s) that relies on it; any form of disclosure, modification, distribution and/or publication of this email is also prohibited.

While all care has been taken, the SEQ Water Grid Manager disclaims all liability for loss or damage to person or property arising from this message being infected by a computer virus or other contamination. Unless stated otherwise, this email represents only the views of the sender and not the views of the SEQ Water Grid Manager and/or the Queensland Government.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Suzie Emery

From:

Bradley John [John.Bradley

Sent:

Sunday, 16 January 2011 7:41 PM

To: Cc: Lance.McCallum : Dan Spiller tim.watts : Barry Dennien

Subject:

Re: Urgent - Cabinet in confidence

Follow Up Flag: Flag Status:

Follow up Flagged

Lance

I am sorry for the delay on the brief requested for tonight for Minister - Barry and his team have been working hard all day on this among their other issues - but have had challenges with input from segwater.

Seqwater has struggled to provide their input in a congent form and so Barry, Dan and others are still there awaiting for some stuff and finalising it at the end of a very long week.

We think we are about 60 to 90 minutes away at this point. I will forward it to you and Minister as soon asap and we vill talk through at 9 am.

John B

From: Bradley John

Sent: Saturday, January 15, 2011 10:33 AM

To: 'Lance.McCallum

<Lance.McCallum >; spiller daniel >; Dennien Barry

Cc: 'tim.watts <tim.watts

Subject: Re: Urgent - Cabinet in confidence

Thanks Lance - we have anticipated the need for something like this - segwgm work underway - I will talk to SEQWGM when out of SDMG now on.

Regards

John B

From: Lance McCallum [mailto:Lance.McCallum]

Sent: Saturday, January 15, 2011 10:30 AM To: spiller daniel ; Bradley John

Cc: Tim Watts <Tim.Watts

Subject: Urgent - Cabinet in confidence

John/Dan

The Minister has asked that preparation be done over the weekend that will enable him to go to the Emergncy Cabinet meeting on Monday with a position on how the Govt is going to handle the issues of reviewing operational decisions made by SEQwater and SEQWGM in relation to releases from the dams.

I understand that in further to the recent independent review of the Wivenhoe operations manual the WGM is also undertaking further work by compiling a list of the operational experts who authored the manual.

Happy to discuss further.

Thanks, Lance.
+
Think B4U Print
1 ream of paper = 6% of a tree and 5.4kg CO2 in the atmosphere
3 sheets of A4 paper = 1 litre of water
++
This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Suzie Emery

From: Sent:

To:

Subject: Attachments:

Dan Spiller [Daniel.Spiller Sunday, 16 January 2011 9:26 PM 'Bradley John' Talking points_Wivenhoe Dam releases Talking points_Wivenhoe Dam releases.docx

For review in case you are still at it.

Dan

CTS No. xxxxx/10

SEQ Water Grid Manager and Seqwater MINISTERIAL BRIEFING NOTE

TO: Minister for Natural Resources, Mines

and Energy and Minister for Trade

January 2011 flood event and Wivenhoe Dam SUBJECT:

operations

REQUESTED BY

The Ministers Office requested this brief by 16 January 2011.

TIMEFRAME

Noting of this brief is required prior to the Emergency Cabinet meeting to be held on 17 January 2011.

RECOMMENDATION

It is recommended that the Minister:

note Segwater's Ministerial briefing note setting out background information on Wivenhoe Dam, the January 2011 flood event and Segwater's Flood Mitigation Manual.

Advisor Ok

Minister.....

☐ Approved ☐ Not Approved ☐ Noted ☐ Further information required

1

1

Dated

Dated

- note the advice on the benefits of pre-emptive releases from Wivenhoe Dam in response to the Minister's request.
- note Mr Brian Cooper's independent compliance review of the operation of Wivenhoe Dam against the Flood Mitigation Manual for the January 2011 flood event.
- approve key media responses on the flood event and Wivenhoe Dam.
- approve that Mr Barry Dennien, Chief Executive Officer, SEQ Water Grid Manager, speak to the media in accordance with the key media responses.

BACKGROUND

- From 13 December 2010 to 11 January 2011, South East Queensland experienced unprecedented rainfall, which resulted in the January 2011 flood event. Wivenhoe Dam played a significant role in mitigating the downstream flood peak.
- Attachment A contains Segwater's Ministerial briefing note setting out background information on Wivenhoe Dam, Wivenhoe Dam's flood mitigation and operations, Segwater's Flood Mitigation Manual, the regulatory context of the Flood Mitigation Manual and Segwater's proposed procedure for the preparation of its comprehensive Flood Mitigation Manual report to the Chief Executive, Department of Environment and Resource Management, on Wivenhoe Dam operations for the January 2011 flood event.
- After the Wivenhoe Dam release in October 2010, by way of a letter dated 25 October 2010 at Attachment B, the Minister requested the SEQ Water Grid Manager to procure urgent advice as to whether South East Queensland's water security situation would provide "an opportunity to reduce the volume stored in key dams as a means of reducing the severity. frequency and duration of flooding in downstream areas."
- The Minister also sought the SEQ Water Grid Manager's "confirmation that these options would not significantly impact upon our current water security, measured as the probability of needing to reintroduce Medium Level Restrictions over the next five to ten years."
- As a result, the SEQ Water Grid Manager requested that Segwater provide a report assessing the options requested by the Minister.

Author	Cleared by	Cleared by	Recommended:
Name: Barry Dennien	Name:	Name:	Name: John Bradley
Position: Chief Executive	Position:	Position:	Director-General, DERM
Officer, SEQ Water Grid	Tel No:	Tel No:	Tel No:
Manage <u>r</u>	Name:	Name:	Date:
Tel No:	Position:	Position:	
Date: 16 January 2011	Tel No:	Tel No:	

725 File Ref: Page 1 of

- Attachment C contains the SEQ Water Grid Manager's letter to the Minister dated 24 December 2010, in response to the pre-emptive Wivenhoe Dam release advice sought, based on Seqwater's advice. This letter stated that "Seqwater has advised that releasing water to below Full Supply Level may provide some benefits in terms of reduced community and operational impacts during minor inflow events, such as has occurred over the past month. For medium and major flood events, it considers that pre-emptive releases will provide negligible benefits...Informed by this advice, the SEQ Water Grid Manager has advised Seqwater that, from a water security perspective, it has no in-principle objection to minor releases from Wivenhoe, Somerset and North Pine dams to minimise the operational and community impacts of gate releases."
- It should be noted that while seeking advice from Seqwater on pre-emptive dam releases, the SEQ Water Grid Manager continued to provide the Department of Environment and Resource Management with progress reports.
- On 11 January 2011, the Minister requested the SEQ Water Grid Manager to procure an
 urgent independent review of Seqwater's operation of Somerset and Wivenhoe Dams in
 accordance with the Flood Mitigation Manual, for the period 13 December 2010 to
 11 January 2011.
- Mr Brian Cooper was engaged to conduct the independent review and his report and curriculum vitae are contained in Attachment D.
- Mr Brian Cooper concludes that the "strategies as set out in the Flood Mitigation Manual have been followed, allowing for the discretion given to making variations in order to maximise flood mitigation effects. The actions taken and decisions made during the Flood Event appear to have been prudent and appropriate in the context of the available knowledge available to those responsible for flood operations and the way events unfolded."

CURRENT ISSUES

- The purpose of this Ministerial brief is to provide the Minister with background information on the January 2011 flood event and the operation of Wivenhoe Dam, in preparation for an Emergency Cabinet meeting scheduled on 17 January 2011.
- This Ministerial brief provides information that may assist in responding to questions raised, or anticipated to be raised, by the public and media.
- Attachment E contains key media responses based on factual information from Seqwater's Ministerial briefing note.

RESOURCE/IMPLEMENTATION IMPLICATIONS

 Any recommendations regarding the Flood Mitigation Manual, improvements to the structure or operation of Wivenhoe Dam, resourcing etc. will arise after any relevant flood event debriefs and Seqwater's Flood Mitigation Manual report to the Chief Executive, Department of Environment and Resource Management.

PROPOSED ACTION

- In accordance with the Flood Mitigation Manual, Seqwater will submit a comprehensive report to the Chief Executive, Department of Environment and Resource Management, containing details of the procedures used, the reasons for such and other pertinent information for the operation of Wivenhoe Dam during the January 2011 flood event.
- This report is required to be submitted within six weeks of completion of the flood event.

I	Author	Cleared by	Cleared by	Recommended:
I	Name: Barry Dennien	Name:	Name:	Name: John Bradley
l	Position: Chief Executive	Position:	Position:	Director-General, DERM
	Officer, SEQ Water Grid	Tel No:	Tel No:	Tel No:
	Manager	Name:	Name:	Date:
	Tel No:	Position:	Position:	
	Date: 16 January 2011	Tel No:	Tel No:	
	* * * *			

File Ref: 726 Page 2 of

UITHER INFORMATION

- Consultation: In preparing the Ministerial briefing note at Attachment A, Seqwater
 consulted with Mr Peter Allen and Mr Bob Reilly from the Office of the Water Supply
 Regulator, Department of Environment and Resource Management. The SEQ Water Grid
 Manager provided information on the Minister's request for advice on pre-emptive releases
 from Wivenhoe Dam and the independent compliance review from Mr Brian Cooper.
- Legislation: The Flood Mitigation Manual is a requirement of, and approved by the Chief Executive, Department of Environment and Resource Management, under the Water Supply (Safety and Reliability) Act 2008.
- Key Communication Messages: The information contained in this Ministerial brief may be used to formulate public messaging regarding the flood event and the operation of Wivenhoe Dam. Communicating the benefits of Wivenhoe Dam for flood mitigation may present positive communication opportunities.


MINISTER'S COMMENTS

ATTACHMENTS

- · Attachment A: Seqwater Ministerial briefing note
- Attachment B: Letter from Minister Robertson to the SEQ Water Grid Manager dated 25 October 2010
- Attachment C: Letter from the SEQ Water Grid Manager to Minister Robertson dated 24 December 2010
- Attachment D: Flood Mitigation Manual compliance review report by Mr Brian Cooper and curriculum vitae of Mr Brian Cooper
- Attachment E: Key media responses

Author	Cleared by	Cleared by	Recommended:
Name: Barry Dennien	Name:	Name:	Name: John Bradley
Position: Chief Executive	Position:	Position:	Director-General, DERM
Officer, SEQ Water Grid	Tel No:	Tel No:	Tel No:
Manager	Name:	Name:	Date:
Tel No:	Position:	Position:	
Date: 16 January 2011	Tel No:	Tel No:	

File Ref: 727 Page 3 of



SeqWater for LIFE

JANUARY 2011 FLOOD EVENT



TABLE OF CONTENTS

1		INT	FRODUCTION	1
2		WI	VENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS	2
	2.	.1	Flood Mitigation	2
	2.	.2	Flood Operations	3
3		MA	ANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS	4
4		JA	NUARY 2011 FLOOD EVENT	6
	4.	.1	Background	6
	4.	.2	Event Decision Making	7
	4.	.3	Flood Mitigation Benefits of Wivenhoe Dam	. 10
5		ΕV	ENT REVIEW	. 12



1 INTRODUCTION

Wivenhoe Dam was constructed by the Queensland Government between 1977 and 1984. The dam is a 56 m AHD high and 2.3 kilometre long earth and rock embankment separated into two parts by a concrete gravity spillway. The spillway is controlled by 5 radial gates, each 12.0 metres wide by 16.0 m AHD high. Two saddle dam embankments are located on the left side of the reservoir.

The dam spillway capacity was upgraded in 2005. This was done primarily through the construction of a 164 metre wide secondary spillway through the right abutment of the existing dam. This spillway contains three erodible earth fill fuse plug embankments that are initiated at different dam levels in excess of EL 75.6.

The dam has two main functions by providing:

- A 1,165,000 ML storage at full supply level (FSL EL 67.0) providing an urban water supply for Brisbane and surrounding areas;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume
 of 1,450,000 ML up to EL77 (this flood level was increased as part the 2005 upgrade
 to allow a water level of EL80m and a temporary flood storage volume of 1,966,000
 ML with all fuse plugs initiated and the dam at the point of failure).

The dam has an EXTREME hazard classification under ANCOLD guidelines because of the significant development downstream in the Brisbane and Ipswich metropolitan areas, with the population at risk in the event of a dam failure numbering in the hundreds of thousands.

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam for dam safety reasons only is scheduled to occur prior to 2035 to enable the dam to safely pass the Probable Maximum Flood. This work will involve the reconstruction of Saddle Dam 2 as a fuse plug spillway.

Wivenhoe Dam is in excellent condition. Comprehensive Dam Safety reviews undertaken in accordance with ANCOLD guidelines have been undertaken in 1997 (Gutteridge, Haskins & Davey Pty Ltd), 2003 (Wivenhoe Alliance), 2006 (NSW Department of Commerce), 2009 (GHD) and September 2010 (Seqwater). The reports concluded that the design of the dam is in accordance with modern day standards and that there are no significant outstanding design or construction issues that require investigation.



2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 Flood Mitigation

The Brisbane River catchment covers an area of approximately 14,000 square kilometres of which about half is below Wivenhoe Dam. Maximum overall flood mitigation effect is achieved by operating Wivenhoe Dam in conjunction with Somerset Dam. Although Somerset and Wivenhoe Dam reduce flooding in Brisbane City, major flooding can still occur. The Lockyer-Laidley Valley drains into the Brisbane River through Lockyer Creek that enters the Brisbane River just downstream of Wivenhoe Dam near Lowood. Another major tributary, the Bremer River, flows into the Brisbane River at Moggill. Wivenhoe Dam has no control over inflows into the Brisbane River from both these major tributaries.

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to minimise flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However, this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as additional inflows after this point would result in a dam failure. Similarly, there will be uncertainty on future rainfall that could occur which could not be releases if there was insufficient flood storage which could not be stored or released.

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.



2.2 Flood Operations

A real time flood monitoring and forecasting system has been established in the Wivenhoe and Somerset Dam catchments. This system employs radio telemetry to collect, transmit and receive rainfall and stream flow information. The system consists of around 230 field stations that automatically record rainfall and/or river heights at selected locations in the dam catchments. Most of these field stations are owned by Segwater with the remainder belonging to other agencies.

The rainfall and river height data is transmitted to Seqwater's Flood Operations Centre in real time. Once received in the Flood Operations Centre, the data is processed using a Real Time Flood Model (RTFM) to estimate likely dam inflows and evaluate a range of possible inflow scenarios based on forecast and recorded rainfall in the dam catchments. The RTFM is a suite of hydrologic computer programs that utilise the real time data to assist in the operation of the dams during flood events.

Seqwater engineers use the RTFM for flood monitoring and forecasting during flood events to operate the dams in accordance with a Manual of Flood Mitigation (the origin of and objectives and procedures contained in the Manual of Flood Mitigation are explained in the following section of this document). Releases of water from the dams are optimised to minimise the impacts of flooding in accordance with the objectives and procedures contained in a Manual of Flood Mitigation.

The RTFM and data collection network performed well During the January 2011 event, with no failures experienced that compromised the ability of Seqwater to operate the dam.



3 MANUAL OF FLOOD MITIGATION FOR WIVENHOE AND SOMERSET DAMS

The Manual of Flood Mitigation for Wivenhoe and Somerset Dams, in its current form, was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

The primary objectives of the procedures contained in the flood manual are, in order of importance:

- Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;
- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers primarily, this involves minimising inundation of the seven bridges below the dam upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.
- Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.



- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life. Under this strategy, the predicted water level is below 68.50 m AHD and the maximum release is 1,900m3/s.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD and the maximum release is less than 3,500m3/s.
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation. Under this strategy, the water level is predicted to be between 68.5 and 74.0 m AHD but the maximum release is less than 4,000m3/s.
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.
 Under this strategy, the water level is predicted to exceed 74.0 m AHD and there is no limit to the maximum release. Consideration is given to managing flood releases to avoid fuse plug initiation if at all possible as this would compromise flood mitigation capacity in the short to medium term.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.



4 JANUARY 2011 FLOOD EVENT

4.1 Background

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML. The details of these events are as follows:

EVENT	EVENT START DATE	EVENT END DATE	VOLUME RELEASED (ML)
1	13/12/2010	16/12/2010	70,000
2	17/12/2010	24/12/2010	150,000
3	26/12/2010	02/01/2010	470,000

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.



		JANUARY 2011 FLOOD	
S	tarting Level	Peak Height	Capacity
%	m AHD	m AHD	%
100	67.0	74.97	191
95	66.5	74.93	191
90	65.8	74.88	190
75	64.0	74.63	187
50	60.0	74.11	180

It should be noted that the possible reductions shown above are based on a dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

4.2 Event Decision Making

The following table contains a summary of the key decisions points associated with the current event. As at 16 January 2011, the event remains in progress.

DATE AND TIME	FLOOD EVENT MILESTONE
07:00 06/01/2011 (Thursday)	Rainfall is experienced in the dam catchments that will result in flood releases, however Wivenhoe releases are delayed for 24 hours to allow Lockyer Creek flood flows to pass downstream and prevent the isolation of the community dependent of Burtons Bridge. The forecast is for 150mm over the next 24 hours.
15:00 07/01/2011 (Friday)	Wivenhoe releases commence, with operational strategy W1 in use. Rainfall for the next four days is estimated to be between 140mm and 300mm, with a forecast for rain easing on Tuesday 11 January 2011. All bridges downstream of the dam with the exception of Fernvale Bridge and Mt Crosby Weir Bridge are expected to be inundated for a number of days.



06:00 09/01/2011	Moderate to heavy rain periods forecast until Tuesday, but both Wivenhoe
(Sunday)	and Somerset dam levels were falling slowly, with Somerset at 1.27 m AHD above FSL and Wivenhoe 1.58 m AHD above FSL.
15:30 09/01/2011 (Sunday)	Following significant rain during the day a meeting of Duty Engineers is held. The QPF issued at 16:00 indicates 50mm to 80mm over the next 24 hours. Based on this forecast, it is anticipated that dam levels can be held to a maximum of 3.50 m AHD above FSL in Somerset and 5.5 m AHD above FSL in Wivenhoe. However, by 19:00 it was apparent that both Fernvale Bridge and Mt Crosby Weir Bridge would be inundated by the combined dam releases and Lockyer Creek flows and that the operational strategy had progressed to W2.
06:30 10/01/2011 (Monday)	Rainfall continued during the night and based on rainfall on the ground it was apparent the operational strategy had progressed to W3.
06:30 10/01/2011 (Monday)	Rainfall continued during the day but based on rainfall on the ground, operational strategy W3 remained in use. However it was apparent that any further heavy rain would result in progression of the operational strategy to W4.
08:00 11/01/2011 (Tuesday)	Rainfall continued during the night with isolated heavy falls in the Wivenhoe Dam catchment area and based on rainfall on the ground it was apparent the operational strategy would soon progress to W4 with Wivenhoe Dam exceeding 8.00 m AHD above FSL. The objective now was to limit outflows and subsequent flood damage to urban areas, while ensuring the structural safety of the dam.
11:00 11/01/2011 (Tuesday)	Rapid inflows were experienced in Wivenhoe Dam, with the dam rising almost a metre in eight hours. Releases were increased until the dam level stabilised in accordance with Strategy W4. Computer models were not reflecting actual dam inflows due to intense point rainfalls in the immediate catchment around the dam. Falls are estimated to be similar to those experienced at both Toowoomba and Upper Lockyer the previous day and are falling outside and between existing rain gauges.
21:00 11/01/2011 (Tuesday)	Wivenhoe Dam peaked. Peak release of 7450 cumecs with a level of 0.7 metres below fuse plug trigger.
22:00 11/01/2011	Wivenhoe Dam releases were closed off as quickly as possible over the



(Tuesday)	next 11 hours, while ensuring water levels in the dam did not rise further and initiate a fuse plug embankment.
08:00 12/01/2011 (Wednesday)	Minimum possible release level reached, with inflows matching outflows. Further reductions in release rate would likely cause the dam level to rise.
21:00 13/01/2011 (Thursday)	The 7 day dam drain down is commenced as Lockyer Creek and Bremer River peaks pass the Lower Brisbane area. Maximum release target is the limit of damaging floods in Brisbane being 3500 cumecs.
09:00 17/01/2011 (Monday)	Drain down continues, with released expected to cease on Wednesday 19 January 2011 unless further rainfall is experienced.




4.3 Flood Mitigation Benefits of Wivenhoe Dam

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam.

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.





JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



The strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area. This was carried out because the releases had stopped the dam from rising and careful monitoring allowed rapid reduction of releases while ensuring fuse plug initiation did not occur.

This notion is supported by BOM.



5 EVENT REVIEW

Under the Manual of Operational Procedures for Flood Mitigation at Wivenhoe Dam and Somerset Dam that are approved and gazetted by the Department of Environment and Resource Management, there is a regulatory requirement that a report must be prepared as per the below wording:

"Sequater must prepare a report after each Flood Event. The report must contain details of the procedures used, the reasons therefore and other pertinent information. Sequater must forward the report to the Chief Executive within six weeks of the completion of the Flood Event."

Such a report was prepared for the flood events of February and March 2010 and copies are available. A copy of the Table of Contents of that report is included as Appendix 1. For this event, the report would be a comprehensive summary of all procedures, actions, outcomes and processes during the event.

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory requirements of the Act and the gazetted manual and any requirements of the Dam Safety Regulator. This would be done within 6 weeks of the closure of the current event as per the manual. This timeframe is subject to any new mobilisation of the Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies



- Review of factors impacting on the protection of urban areas
- Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices desirable to improve Seqwater's ability to manage events? For example, investigations to raise the dam to improve its flood storage capacity, If so, what are they and their implications.
 - Are changes to the facilities or work practices of other organisations desirable to improve Seqwater's abilities to manage these events?
 - whether it is worth investigating increasing the flood capacity of Wivenhoe
 - whether the Brisbane River crossings which act, under some situations as a constraint on the releases from Wivenhoe, should be replaced by bridges. For example if the smallest could pass, for example, 2,500 cumecs, then this could enable higher releases under some circumstances.
 - Whether the policy of draining the flood compartment within 7 days should be modified.
 - Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert panel of
 review including representatives of DERM, Seqwater, BoM, affected Local Governments
 and other stakeholders as necessary.



Appendix A



FINAL REPORT – FLOOD EVENTS AT WIVENHOE, SOMERSET AND NORTH PINE DAMS FOR FEBRUARY AND MARCH 2010

TABLE OF CONTENTS

1.0 INTRODUCTION	1
2.0 FLOOD EVENT SUMMARY	2
2.1 FEBRUARY 2010	2
2.2 MARCH 2010	3
3.0 MOBILISATION AND STAFFING	5
3.1 16тн ТО 18тн FEBRUARY 2010	5
3.2 1sт TO 4тн MARCH	5
3.3 5тн ТО 6тн MARCH	5
3.4 6тн ТО 7тн MARCH	6
3.5 10тн ТО 11тн MARCH	6
4.0 EVENT RAINFALL	7
4.1 FEBRUARY 2010	7
4.2 MARCH 2010	9
5.0 INFLOW AND RELEASE DETAILS	12
5.1 16тн ТО 18тн FEBRUARY 2010	12
5.2 1st MARCH 2010	15
5.3 6 / 7тн MARCH 2010	18
5.4 11тн MARCH 2010	21
6.0 DATA COLLECTION SYSTEM PERFORMANCE	25
6.1 NETWORK AVAILABILITY	25
6.2 RAINFALL	25
6.3 STREAM HEIGHT	26
6.3.1 Main Stream	26
6.3.2 Back-up Stream	27
6.3.3 Headwater Sensors	
6.3.4 Sensor Calibration	
6.3.5 Stream Height Rating Curves	
7.0 DATA ANALYSIS PERFORMANCE	
7.1 RUNOFF-ROUTING MODELS	
7.2 BASEFLOW ASSESSMENT	29

8.0 COMMUNICATIONS	31
8.1 EVENT LOG	31
8.2 DECLARATION OF EVENT MOBILISATION	31
8.3 SHIFT HANDOVER	32
9.0 FLOOD MANAGEMENT STRATEGIES	33
9.1 16тн ТО 18тн FEBRUARY 2010	33
9.1.1 North Pine Dam	33
9.2 26TH FEBRUARY TO 4TH MARCH	35
9.2.1 Somerset and Wivenhoe Dam	35
9.2.2 North Pine Dam	38
9.3 4TH MARCH TO 7TH MARCH	41
9.3.1 North Pine Dam	41
9.4 10тн MARCH TO 11тн MARCH	44
9.4.1 North Pine Dam	44
10.0 RECOMMENDATIONS & CONCLUSIONS	46
10.1 DATA COLLECTION	46
10.2 DATA ANALYSIS	46
10.3 DIRECTIVES AND STATUS REPORTS	46
10.4 OPERATIONAL STRATEGIES	47

LIST OF APPENDICES

APPENDIX A - FOC Attendance Logs & Event Logs

APPENDIX B - Estimated Inflows and Release


APPENDIX C - Reservoir Headwater Levels

LIST OF TABLES

Table 2.2: Dam Operations in March 2010 3 Table 4.1: February 2010 Sub-Catchment Rainfalls (mm) 7 Table 4.2: March 2010 Sub-Catchment Rainfalls (mm) 9 Table 5.1: Peak Flood Level and Flows – 16th to 18th February 2010 12 Table 5.2: Somerset Dam – 16th February to 20th February 2010 14 Table 5.3: Wivenhoe Dam – 16th February to 20th February 2010 14 Table 5.4: North Pine Dam – 16th February to 18th February 2010 14	Table 2.1: Storage Status Prior to February 2010 Event	2
Table 4.2: March 2010 Sub-Catchment Rainfalls (mm)9Table 5.1: Peak Flood Level and Flows – 16th to 18th February 201012Table 5.2: Somerset Dam – 16th February to 20th February 201014Table 5.3: Wivenhoe Dam – 16th February to 20th February 201014	Table 2.2: Dam Operations in March 2010	3
Table 5.1: Peak Flood Level and Flows – 16th to 18th February 2010	Table 4.1: February 2010 Sub-Catchment Rainfalls (mm)	7
Table 5.2: Somerset Dam – 16th February to 20th February 2010	Table 4.2: March 2010 Sub-Catchment Rainfalls (mm)	9
Table 5.3: Wivenhoe Dam – 16th February to 20th February 201014	Table 5.1: Peak Flood Level and Flows - 16th to 18th February 2010	12
	Table 5.2: Somerset Dam – 16th February to 20th February 2010	14
Table 5.4: North Pine Dam – 16th February to 18th February 201012	Table 5.3: Wivenhoe Dam – 16th February to 20th February 2010	14
	Table 5.4: North Pine Dam – 16th February to 18th February 2010	14



Table 5.5: Peak Flood Level and Flows – 1st March 2010	15
Table 5.6: Somerset Dam – 24տ February to 18տ March 2010	17
Table 5.7: Wivenhoe Dam – 24th February to 18th March 2010	17
Table 5.8: North Pine Dam – 26տ February to 4տ March 2010	18
Table 5.9: Peak Flood Level and Flows – 6/7տ March 2010	19
Table 5.10: North Pine Dam – 4th March to 6th March 2010	21
Table 5.11: Peak Flood Level and Flows – 11տ March 2010	22
Table 5.12: North Pine Dam – 10տ March to 11տ March 2010	24
Table 9.1: North Pine Dam Gate Settings – 17տ to 18տ February 2010	35
Table 9.2: Somerset Dam gate Settings – 24տ February 18տ March	37
Table 9.3: North Pine Dam Gate Settings – 1st to 4th March 2010	39
Table 9.4: North Pine Dam Gate Settings – 5տ to 7տ March 2010	42
Table 9.5: North Pine Dam Gate Settings – 10th to 11th March 2010	45





TRIM reference: D/11/	Enquiry received:
Purpose: Wivenhoe Dam release	

Impacts of Wivenhoe and Somerset dams

- · Wivenhoe and Somerset dams reduced the flood peak by 2.5 metres in the City and 5.5 metres at Moggill.
- Without the dams, up to 13,000 more houses would have been flooded. They prevented up to \$1.6 billion of damages.
- Without the dams, major flooding would have lasted for three days.
- Wivenhoe and Somerset dams controlled 2.6 million megalitres of floodwater. This is 1.1 million megalitres more than in 1974.
- The dams controlled these floodwaters, providing time for peak flows from the Lockyer and Bremer to pass.
- Total flow in the Brisbane River in 1974 was 9,500 cubic metres per second. The estimated flow from this event would have been 13,000 cubic metres per second if Wivenhoe did not exist.

Operation of Wivenhoe and Somerset dams

- The dams were operated strictly in accordance with the approved Operational Procedures.
- The Operational Procedures were developed by Australia's best hydrologists, including:
 - o Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland
 - Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.
- Professor Apelt is Chair of the Brisbane City Council flood taskforce.

Rainfall forecasts

- Dam operations were based on forecasts provided by the Bureau of Meteorology.
- The rainfall during the event exceeded all forecasts.

- Rainfall was local and intense, as demonstrated by the tragic events in Toowoomba.
- It is unreasonable to expect that dam operators could foresee these events.

Pre-emptive releases

- The dam has been designed for both water supply and flood mitigation.
- Detailed Operational Procedures have been developed by leading hydrologists over many years, with a review as recently as 2009. The procedures are based on the current full supply level.
- Water was released from the dam on 20 of the 25 days leading up to this
 event.
- A total of 1,450 million megalitres was released between October 2010 and this event.
- These releases isolated some residents and inconvenienced many more.
- The clear decision making process in the Manual was set down since 1992 and was reviewed in 2009 to reflect the installation of the Wivenhoe Spillway upgrade. That review included independent experts from the Bureau of Meteorology, Sunwater, Brisbane City Council and the Department of Environment and Resource Management.
- It is a manual which reflects safe operating practices based on detailed hydrological analysis and technical assessments of dam safety.

Peak releases

- Outflows from Wivenhoe Dam peaked on Tuesday 11 January 2011 at 397,000 ML.
- The impact of these releases was minimised by closing down releases quickly once inflows into the dam had peaked.
- The release rate was higher for three hours, but not sustained.
- These releases accounted for only part of the increase in river levels. The Bureau of Meteorology has stated that, even at their peak, outflows from Wivenhoe Dam contributed slightly more than half the flood arriving in Brisbane (Courier Mail, 14 January).

Large releases earlier

- Releasing large volumes of water over the weekend would have had major impacts on the rural communities of the Brisbane Valley. Bridges would have been cut and communities would have been isolated with little notice.
- Over the weekend, neither rainfall forecasts nor the rain on the ground indicated with certainty that urban areas would be impacted.

Increases to above 200% (level of fuse plugs)

- Wivenhoe Dam is not designed to overtop. If it did, the dam would fail and the
 resulting damage and loss of life would be at least 100 to 1,000 times greater
 than that currently being experienced.
- To ensure that this never occurs, the dam has been designed with plugs that automatically open when it reaches more than 200% of full supply volume.
- Once opened, the rate of release through these plugs cannot be varied.
- The plugs continue to release water at this rate until the dam reaches full supply level.
- The plugs would take four to six months of dry weather to repair, rendering the flood storage compartment useless.

Changes to dam operations

- The upgrade required to meet ANCOLD standards would have had no impact on this event. It will be completed for even bigger floods.
- Options to increase the full supply level have been investigated. Had they been implemented, these options would have reduced the flood compartment, resulting in higher releases earlier.

Ministerial Briefing Note 17 January 2010 Flood Event January 2011

1. BACKGROUND INFORMATION ON WIVENHOE DAM

- 2. WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS
- 2.1 What were the benefits provided by Wivenhoe Dam during the current event?
- 2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?
- 2.3 What is the role of the erodible fuse plug embankments?
- 2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?
- 2.5 Is there a detailed record of the events associated with the current flood?
- 3. THE MANUAL OF OPERATIONAL PROCEDURES FOR FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM
- 3.1 What is the Manual of Flood Mitigation and how was it developed?
- 3.2 What is contained in the Manual?
- 4. REGULATORY CONTEXT
- 5. SEQWATER REPORT

1 BACKGROUND INFORMATION ON WIVENHOE DAM

Wivenhoe Dam was completed in 1984 and has two main functions;

- A 1,165,000 ML storage providing an urban water supply for Brisbane;
- Flood mitigation in the Brisbane River by providing a dedicated flood storage volume of 1,450,000 ML (this flood storage was increased in 2005 to 1,966,000 ML with the dam at the point of failure).

In accordance with the Queensland Regulatory program for dam spillway upgrades, a further upgrade of Wivenhoe Dam is scheduled to occur prior to 2035 but only for dam safety reasons in the event of a probable maximum flood and has no impact on the current event.

Wivenhoe Dam is in excellent condition with four Comprehensive Dam Safety reviews undertaken in the last 14 years, the latest in 2010.

2 WIVENHOE DAM FLOOD MITIGATION AND FLOOD OPERATIONS

2.1 What were the benefits provided by Wivenhoe Dam during the current event?

The following graphs demonstrate the significant benefits of Wivenhoe Dam in mitigating the current flood event, with reductions in flood peak from Wivenhoe Dam not existing of up to 2.5 metres in the City area and up to 5.5 metres in the Moggill area further upstream.


This equates to significant reduction in the potential for loss of life as well as saving in damages in the order of up to \$1.6 billion based on current damage curves. Up to 13,000 more properties would have been impacted by the event without the Dam. (Source: Flood Damage Tables provided to Seqwater by the Brisbane City Council).

The time at which flood levels remained elevated above major levels has also been reduced by up to 3 days by the dam. This has significant benefits to impact on the population of the city, property damage and the recovery operation.


Depending on the nature of the event, the presence of Wivenhoe Dam could also potentially increase flood warning times to impacted areas. How these times may have been increased during the current event is presently difficult to quantify, but discussions will be held with BOM on this issue at a later date.

In addition, the strategy adopted to quickly close off releases once the peak in the dam had been reached and rain stopped falling certainly reduced the predicted flood peak by at least one metre in the lower Brisbane River area. This was carried out because the releases had stopped the dam from rising and careful monitoring allowed rapid reduction of releases while ensuring fuse plug initiation did not occur.

JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Brisbane City



JANUARY 2011 BRISBANE FLOOD Assessment of Flood Levels at Moggill



4|Page

2.2 Why was Wivenhoe Dam only allowed to rise up to 191% and not 230%?

Wivenhoe Dam mitigates downstream flooding by storing incoming flood water during a rainfall event and releasing these waters at a reduced flow rate downstream to reduce flood impacts. The timing of the releases is also manipulated so that the aim is for outflows from the dams to impact on downstream areas only after the peak inflows from the downstream major tributaries have passed. However this aim cannot always be achieved in practice. This is because some large floods, such as the one currently being experienced, have the potential to overflow the dam's flood storage compartment. Should this occur, the dam would fail and the resulting damage and loss of life would be at least 100 to 1000 times greater than that currently being experienced.

Therefore the basis of all flood operation decision making is to ensure the dam never fails. This is the reason that the dam's flood storage compartment would never be intentionally fully filled as any additional inflows after this point would result in a dam failure. At any one time, there will always be uncertainty about what rain is going to occur. Hence, we cannot use all of the flood capacity as we would not be able to release sufficient water to cater for large inflows.

2.3 What is the role of the erodible fuse plug embankments?

Another factor that impacts on flood release decision making in large events are the levels at which the erodible fuse plugs are triggered. The fuse plugs act as a safety valve to rapidly increase dam outflows if the structural safety of the dam is in danger. Loss of one or more fuse plugs severely limits the ability of the dam to mitigate the effects of future flood events that may occur prior to the fuse plug or plugs being reinstated. Reinstatement of a fuse plug following an event would take a minimum of 4 to 6 months and would require an extended period of relatively dry weather.

2.4 Why weren't pre-emptive releases undertaken prior to the start of the flood event?

In the 25 days leading up to the current event, three flood events impacting on Wivenhoe Dam were experienced, with gate releases being made on all but five of those days. The total outflow from these events was around 700,000ML.

During these events, requests were received from Councils and residents impacted by bridge closures downstream of the dam to curtail releases as soon and as quickly as possible. Additionally the 2 January end date of the flood event prior to the current event meant that significant drain down of the dam prior to the onset of the current event that commenced on 6 January 2011, was not possible without major bridge inundation downstream of the dam and without exceeding minor flood levels in the lower Brisbane River.

Additionally, a flood event was also experienced in October 2010 that resulted in a release of 750,000ML from the dam. Accordingly drain down below the dam full supply level prior to the start of the first December event would not have been possible without significant bridge inundation and without exceeding minor flood levels (as defined by BOM and BCC) in the lower Brisbane River.

Regardless, significant drain down prior to the current event would have had little impact on the peak level in Wivenhoe Dam as shown in the table below. The reason for this is that this total event inflow volume of 2,600,000 ML is well in excess of the useable flood storage combined with the available water supply storages shown in the table.

The specific impact on the Lower Brisbane River of these reduced dam levels requires the use of a complex hydraulic model. The results of this modelling would still contain a degree of uncertainty as illustrated by the difficulties in estimating the final flood peak in Brisbane during the event. This is because the rapid closure of the gates after peak inflow was achieved resulted in significant water level reductions downstream and this is difficult to model accurately.

		JANUARY 2011 FLOOD	
Sta	rting Level	Peak Height	Capacity
%	m AHD	m AHD	%
100	67.0	74.97	191
95	66.5	74.93	191
90	65.8	74.88	190
75	64.0	74.63	187
50	60.0	74.11	180

It should be noted that the possible reductions shown above are based up a unique dual peaked flood hydrograph with a volume of about 2,600,000 ML which occurred during this event. A hydrograph with the same volume but a different distribution could result in a significantly lower reduction in peak water levels.

Flood operations at the dam are also highly dependent upon the flood inflow volume and a slight variation in the flood volume could significantly reduce the benefits associated with draining down the dam prior to a flood event.

2.5 Is there a detailed record of the events associated with the current flood?

A preliminary report has been prepared and is attached to this briefing.

3 THE MANUAL OF FLOOD MITIGATION AT WIVENHOE DAM AND SOMERSET DAM

3.1 What is the Manual of Flood Mitigation and how was it developed?

The Manual of Flood Mitigation for Wivenhoe and Somerset dams in its current form was developed in 1992 during an extensive hydrological study of the Brisbane and Pine Rivers catchments by DPI, Water Resources. The final reports were subject to extensive internal review by the Water Resources Group before being reviewed by an independent review panel comprising Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland and Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer Water Resources, Snowy Mountains Engineering Corporation.

Subsequently, the Manual was extensively reviewed during the Brisbane Valley Flood Damages Minimisation Study in 2006, with the latest comprehensive review of the Manual undertaken in 2009. Both of these reviews have included expert review panels comprising key stakeholders, with the most recent review involving representatives from DERM, BOM, BCC and SunWater.

The Manual of Flood Mitigation is prepared by Seqwater as the owner of the dam and approved and gazetted by the Chief Executive of DERM in accordance with the Water Supply Act 2008. The manual defines flood objectives procedures; roles and responsibilities; and staffing and operational requirements for flood events impacting on Wivenhoe and Somerset dams.

3.2 What is contained in the Manual?

The primary objectives of the procedures contained in the Manual are, in order of importance:

- Ensure the structural safety of the dams;
- Provide optimum protection of urbanised areas from inundation;
- Minimise disruption to rural life in the valleys of the Brisbane and Stanley Rivers
 primarily, this involves minimising inundation of the seven bridges below the dam
 upstream of Moggill);
- Retain the storage at Full Supply Level at the conclusion of the Flood Event.

 Minimise impacts to riparian flora and fauna during the drain down phase of the Flood Event.

During an event, the operation of the dam transitions between the following four operating strategies depending of the circumstances at the time. These procedures associated with these strategies are explained in detail in the Manual.

- Strategy W1 Primary consideration is given to Minimising Disruption to Downstream Rural Life.
- Strategy W2 Transition Phase moving from Minimising Disruption to Protecting Downstream Urban Areas.
- Strategy W3 Primary consideration is to Protect of Urban Areas from Inundation.
- Strategy W4 Primary consideration is to protecting the structural safety of the Dam.

In addition to these strategies, historical records show that there is a significant probability of two or more flood producing storms occurring in the Brisbane River system within a short time of each other. Accordingly for each flood event, the aim is always to empty stored floodwaters within seven days after the flood peak has passed through the dams.

4 REGULATORY CONTEXT

Operational procedures for flood mitigation for a dam are contained in the Flood Mitigation Manual approved under sections 370 to 374 of the *Water Supply (Safety and Reliability) Act 2008* (Water Supply Act). Under section 370 of the Water Supply Act, Seqwater as the owner and operator of Wivenhoe and Somerset Dams is required to prepare a Flood Mitigation Manual. The Chief Executive (CE) of DERM (or his delegate) approves the Flood Mitigation Manual, and the approval is notified in the Queensland Government Gazette. Approval can be for a period of up to five years, after which the approval needs to be renewed. There are no decision-making criteria specified in the Water Supply Act for the CE to take into account when approving the Flood Mitigation Manual.

The Flood Mitigation Manual requires, amongst other matters:

- Flood operations to be conducted in accordance with manual's provisions, unless
 Seqwater considers that it is necessary to depart from the procedures of the Flood
 Mitigation Manual to meet the flood mitigation objectives of the Flood Mitigation Manual.
 The Flood Mitigation Manual sets out a consultation and approval process through
 Seqwater's Chair and the CE for departures from the Flood Mitigation Manual. This
 discretion was not exercised in the January 2011 flood event.
- 2. Flood operations to be under the control of CE-approved engineers (who are highly qualified and experienced)
- 3. Annual reporting on the preparedness and status of the flood control system for flood operations, and the training of the personnel who manage the flood events.
- 4. Reporting on the flood operations during flood events.
- Reviews after flood events such as the January 2011 event, and a Seqwater report
 containing details of the procedures used, the reasons for such and other pertinent
 information. Seqwater must forward this report to the CE within six weeks of the
 completion of a flood event.

Section 374 of the Water Supply Act protects the CE and Seqwater from liability for complying with the Flood Mitigation Manual. It states:

- (1) The chief executive or a member of the council does not incur civil liability for an act done, or omission made, honestly and without negligence under this part.
- (2) An owner of a dam who observes the operational procedures in a flood mitigation manual, approved by the chief executive, for the dam does not incur civil liability for an act done, or omission made, honestly and without negligence in observing the procedures.

During November 2010, Commonwealth, State and local government agencies developed a Protocol for Communication of Flooding Information for the Brisbane River Catchment — including Floodwater Releases from Wivenhoe and Somerset Dams to "ensure the provision of consistent and robust information to the community". This is separate from the Flood Mitigation Manual, is not legally binding and is not subject to regulatory approval/review.

Some DERM staff, because of their specialist skills, work in the Flood Operations Centre that Sequater activates to manage such events in accordance with the Flood Mitigation Manual. The Flood Operations Centre is not involved in any of the regulatory decisions concerning the dams or are members of the Office of the Water Supply Regulator,

Department of Environment and Resource Management, which undertakes the CE's regulatory functions.
11 Page

5 SEQWATER REPORT

It is recommended that the process and content for reports required for this event be:

- In the short term, utilise this report attached to this briefing note as the basis for communications and discussion.
- Prepare any Interim Reports as agreed to provide information and input as required.
- Seqwater prepare a Comprehensive Report as per the existing regulatory
 requirements of the Act and the gazetted manual and any requirements of the Dam
 Safety Regulator. This would be done within 6 weeks of the closure of the current
 event as per the manual. This timeframe is subject to any new mobilisation of the
 Flood Operations Centre. The Table of Contents would include:
 - Introduction
 - Flood Event Summary
 - Mobilisation and Staffing
 - Event Rainfall
 - Inflow and Release Details
 - Data Collection System Performance
 - Data Analysis Performance
 - Communication
 - Flood Management Strategies and Manual Compliance
 - Improvements in data collection systems, practices and processes.
 - improvements by interacting agencies
 - Review of factors impacting on the protection of urban areas
 - Recommendations & Conclusions
- The report would then be reviewed by the Dam Safety Regulator in conjunction with any peer review they require. The review should cover:
 - Were the provisions of the manual complied with?
 - What improvements to either facilities e.g. stream gauges, or work practices, are desirable to improve Sewater's ability to predict inflows into the dams.
 - Are improvements to either Seqwater's facilities or work practices desirable to improve Seqwater's ability to manage events? For example, investigations to raise the dam to improve its flood storage capacity, If so, what are they and their implications

- Are changes to the facilities or work practices of other organisations desirable to improve Sequeter's abilities to manage these events?
- whether it is worth investigating increasing the flood capacity of Wivenhoe
- whether the Brisbane River crossings which act, under some situations as a constraint on the releases from Wivenhoe, should be replaced by bridges. For example if the smallest could pass, for example, 2,500 cumecs, then this could enable higher releases under some circumstances.
- Whether the policy of draining the flood compartment within 7 days should be modified.
- Given the manual's order of priorities i.e. protection of the dam etc, are any changes in the flood release strategies for either dam desirable? If so, what are they, and their implications
- Based on this review, a review of the Manual of Operational Procedures for Flood
 Mitigation at Wivenhoe Dam and Somerset Dam would occur utilising an expert
 panel of review including representatives of DERM, Seqwater, BoM, affected Local
 Governments and other stakeholders as necessary.





TRIM reference: D/11/	Enquiry received:	
Purpose: Wivenhoe Dam release		

Impacts of Wivenhoe and Somerset dams

- Wivenhoe and Somerset dams reduced the flood peak by 2.5 metres in the City and 5.5 metres at Moggill.
- Without the dams, up to 13,000 more houses would have been flooded. They prevented up to \$1.6 billion of damages.
- Without the dams, major flooding would have lasted for three days.
- Wivenhoe and Somerset dams controlled 2.6 million megalitres of floodwater.
 This is 1.1 million megalitres more than in 1974.
- The dams controlled these floodwaters, providing time for peak flows from the Lockyer and Bremer to pass.
- Total flow in the Brisbane River in 1974 was 9,500 cubic metres per second.
 The estimated flow from this event would have been 13,000 cubic metres per second if Wivenhoe did not exist.

Operation of Wivenhoe and Somerset dams

- The dams were operated strictly in accordance with the approved Operational Procedures.
- The Operational Procedures were developed by Australia's best hydrologists, including:
 - Professor Colin Apelt, Head of Department, Department of Civil Engineering, University of Queensland
 - Mr Eric Lesleighter, Principal Hydraulic Engineer and Chief Engineer
 Water Resources, Snowy Mountains Engineering Corporation.
- Professor Apelt is Chair of the Brisbane City Council flood taskforce.

Rainfall forecasts

- Dam operations were based on forecasts provided by the Bureau of Meteorology.
- The rainfall during the event exceeded all forecasts.

- Rainfall was local and intense, as demonstrated by the tragic events in Toowoomba.
- It is unreasonable to expect that dam operators could foresee these events.

Pre-emptive releases

- The dam has been designed for both water supply and flood mitigation.
- Detailed Operational Procedures have been developed by leading hydrologists over many years, with a review as recently as 2009. The procedures are based on the current full supply level.
- Water was released from the dam on 20 of the 25 days leading up to this
 event.
- A total of 1,450 million megalitres was released between October 2010 and this event.
- These releases isolated some residents and inconvenienced many more.
- The clear decision making process in the Manual was set down since 1992 and was reviewed in 2009 to reflect the installation of the Wivenhoe Spillway upgrade. That review included independent experts from the Bureau of Meteorology, Sunwater, Brisbane City Council and the Department of Environment and Resource Management.
- It is a manual which reflects safe operating practices based on detailed hydrological analysis and technical assessments of dam safety.

Peak releases

- Outflows from Wivenhoe Dam peaked on Tuesday 11 January 2011 at 397,000 ML.
- The impact of these releases was minimised by closing down releases quickly once inflows into the dam had peaked.
- The release rate was higher for three hours, but not sustained.
- These releases accounted for only part of the increase in river levels. The Bureau of Meteorology has stated that, even at their peak, outflows from Wivenhoe Dam contributed slightly more than half the flood arriving in Brisbane (Courier Mail, 14 January).

Large releases earlier

- Releasing large volumes of water over the weekend would have had major impacts on the rural communities of the Brisbane Valley. Bridges would have been cut and communities would have been isolated with little notice.
- Over the weekend, neither rainfall forecasts nor the rain on the ground indicated with certainty that urban areas would be impacted.

Increases to above 200% (level of fuse plugs)

- Wivenhoe Dam is not designed to overtop. If it did, the dam would fail and the resulting damage and loss of life would be at least 100 to 1,000 times greater than that currently being experienced.
- To ensure that this never occurs, the dam has been designed with plugs that automatically open when it reaches more than 200% of full supply volume.
- Once opened, the rate of release through these plugs cannot be varied.
- The plugs continue to release water at this rate until the dam reaches full supply level.
- The plugs would take four to six months of dry weather to repair, rendering the flood storage compartment useless.

Changes to dam operations

- The upgrade required to meet ANCOLD standards would have had no impact on this event. It will be completed for even bigger floods.
- Options to increase the full supply level have been investigated. Had they been implemented, these options would have reduced the flood compartment, resulting in higher releases earlier.