Name of Witness	Kathleen Mary WILSON	
Date of Birth	A self-transfer to the self-tr	
Address and contact details	Shellcott Street, Toogoom	
Occupation	Self Employed Cleaner	
Officer taking statement	Det Insp Mark Ainsworth	
Date taken	31/8/11	

Kathleen Mary WILSON states;

- 1. I am a year old woman residing in a low set house situated at Shellcott Street, Toogoom. My former husband and I myself built this house in 1985 and moved in on the construction being completed. At the time of constructing the house there was natural bushland located behind our house to the south west. This bushland was a large corridor separating our residence from O'Regan Creek Road, Toogoom. Our actual land sat slightly above the natural bushland level and had a small slope dropping about 6 inches from the back of the actual house to the commencement of the bushland. My property is zoned residential and is in the Parish of Vernon within the described as lot on Fraser Coast Regional Council. There are no industrial premises in the area. In recent years a number of new residential developments have been established dividing the community up between old residential and new residential. Prior to Council Amalgamation the council for this area was the Hervey Bay City Council.
- 2. Shortly after moving into the house, my husband and I levelled up the back yard, providing a level area for our children to play on. Our land was still marginally higher than that of the natural bushland.



Exhibit Number:



I had a 6 foot timber fence constructed at the rear of my property about 3 and a half years ago separating my residence from the new development behind.

- 3. I do recall around 1989/90; there was minor flooding in the area. The area of the bushland flooded and pushed approximately 2 inches of water across our backyard. This water did not enter our house.
- 4. On purchasing the land, I didn't realise that the property would be subject to flooding. I recall the flooding events of December, 2010 and January, 2011. At the time of the first flooding event on 28th December, 2010 I was away on holidays, but have been provided a written version by my brother of the events of this flooding. was present at my house when this flooding occurred. He wrote three pages of handwritten notes at the time of the flooding and left the notes at my house to provide me with an explanation of what occurred. I have retained these notes and can now provide them to the Commission.

I now produce 3 pages of notes written by describing the flood events of 28 December, 2010. (A)

5. This letter provides a good description of water levels, SES response, Council response and some suggestions of sewerage flowing amongst the flood waters.





400 George Street Brisbane GPO Box 1738 Brisbane Queensland 4001 Australia Telephone 1300 309 634 Facsimile +61 7 3405 9750 www.floodcommission.qld.gov.au ABN 65 959 415 158

- 6. At the time of the flood my brother removed property and placed it in the shed located at the rear of our yard in an attempt to keep it dry. After I arrived home on 6th January, 2011, I managed to contact Council. Flood waters rose up again in early January, 2011 however not to the level of what occurred at Christmas time.
- 7. I was seeking their assistance to prevent flood water entering my house. Council advised me to contact SES who told me it was a Council matter. Council then told me to contact SES and after the run around SES arrived at my residence and assisted me with bags and plastic to prevent the waters from entering my house. Flooding to my residence was caused by a new residential development that has been established at the rear of my property where the bushland formerly was.
- 8. About fifteen years ago, developers commenced this new residential development. They raised the level of the former bushland to be a height of about one metre higher than my rear yard. The developers constructed a drain/easement at the rear of my fence in between my fence and the boundary line of the new residences. With this new estate being raised my property, in times of rain like that in December and January floods, water flows from this development in the direction of my residence, causing flooding. I would best describe the drain/easement as a tool to take away running water however there is no pit of substantial drain for the collected water to run into for dispersion.





- 9. The new residences have built bluescope steel fences up to the older residences fence lines. These fences cross the easement/drain and sit at ground level, preventing water to flow freely away. I do not understand how Council would approve this situation.
- 10. The existing flood situation would not have occurred if the drain/easement was not impeded by bluescope steel fences or if the Council had a drain at the easement for the water to flow into to take the water away. It is to the detriment to the house owners in Shellcott Street that adequate drainage was not installed at the time this development was constructed.
- 11.Prior to the development commencing many Shellcott Street residents and other residents from nearby areas submitted objections to the Council regarding the destruction of the existing bushland and the location of the development. My objection was based solely on the destruction of the bushland. I actually hand delivered the objection to the counter person at the Council. I did not hear anything back regarding my objection. I later rang Council when I heard bulldozers felling trees to the rear of my property, and informed them that I had previously lodged an objection re the development of this area. The Council officer told me that they had received my letter of objection however it was too late, as the period for objections had expired. The Council employee told me I could take up my objections with the developer.





400 George Street Brisbane GPO Box 1738 Brisbane Queensland 4001 Australia Telephone 1300 309 634 Facsimile +61 7 3405 9750 www.floodcommission.qld.gov.au ABN 65 959 415 158

- 12.On 14th March, 2011, I contacted Council raising my concerns with them regarding the flooding of my premises. As a result of this phone conversation, the Infrastructure Engineer for the Fraser Coast Council conducted an on site inspection of my property regarding my concerns. On 23rd March, 2011 I received a letter back from the Infrastructure Engineer of the Fraser Coast Regional Council. His letter covers three issues, these being:
 - The recent development at the rear of my premises.
 - Two of the stormwater pipes discharging onto my property.
 - There is a pit of some kind discharging onto my property.
- 13. His responses to these questions have been provided to investigators at the Floods Commission of Inquiry.

I now produce a 2 page letter under the hand of the Infrastructure Engineer, Fraser Coast Regional Council. (β)

- 14.At point 1 in the response letter, I find it interesting that a fence does not constitute a permanent piece of work particularly when the fences were not removed at the time of the floods and clearly impeded the flow of water in the easement/drain.
- 15.I was present when investigators took photographs of my yard and the adjoining residential development including the fences blocking the easement.



I now produce a series of photographs of my residence and surrounding structures mentioned in this statement. (C)

K.M.WILSON

Justices Act 1886

I acknowledge by virtue of section 110A(5)(c)(ii) of the Justices Act 1886 that:

- (1) This written statement by me dated 31-8-11 and contained in the pages numbered 1 to is true to the best of my knowledge and belief; and
- (2) I make this statement knowing that, if it were admitted as evidence, I may be liable to prosecution for stating in it anything that I know is false.

.....Signature

Signed at Tookoom this 28 H day of SEPTEMBER 2011





SHELLOT LAKE FLEXES ITS MUSCLE SHELLOT LAKE PLEXES 175 MUSCLE The STEMBER 2010. The water around this home at SHELL COT 5T. I 000 gom seems to have stopped riving. We are in a lake of water which spreads from a large wain at the rear of the property to fine paces from the BITUMEN ROAD to the EAST, this lake extends from the South, at NO 1 at hop and ig continues up to my waist on af SHELL COT ST granthed in this lake from South to north sometimes up to my waist and at times 6-12 inches doop. My berambulations to be a passed in the point in the lake where water gould escape atter than down through the saturated samps force and the firl of SES papelle battled to no abail to heep the water at shoop have and the firl of the property water at places it small available on the lake water at places it small as if the sewage was the flooded abad discelling was pumped clear and sandragged was pumped clear and sandragged. This drama averyone g opposed to who

had tried to contact council sorries
for help with a pump or advice on what could be done
to all inte the problem had not been able to reach Council Staff.
all of the flooding could have been
helped or avoided with the supply
at a reasonable pump. Not one
word or person game to loook,
or adress the streets problem in
this 12 hour period. I personally
wolked through the lafte I have
described at the height (so for) of
the water. My name is

Shellest st at this time
and was resident at

street water from the loodly affected shollcot St at this time at a low point in the attack water from the body affected dwelling was purphed to the street and drained through a rocant lot toward the seaword dune area. This love point is at the fire and SES shod and the single lane traffic calming structure 99 f heavy rain was to come tonight them I there is little doubt that the lake 9 have described will enter a few more homes and shods as 9 said there does not appear to be an outlet for the drains constructed in the lake (ie) they fill with water quite nicely and then have no

where to empty into It come rough out let was made at the shop area than the described lake would at least not get to a height where it would enter homes and sheds.

28:12:2010



23 March 2011

Kathleen Wilson
Shellcot Street
Toogoom QLD 4655

PO Box 1943 Hervey Bay Qld 4655

T 1300 794 929 F (07) 4197 4455 E enquiry@frasercoast.qld.gov.au www.frasercoast.qld.gov.au

Dear Kathleen

DRAINAGE CONCERN - SHELLCOT STREET TOOGOOM

I refer to your telephone enquiry dated 14 March 2011 regarding the above matter.

Thank you for making yourself available for the onsite inspection, as a result of that inspection I can make the following comments.

There are several issues occurring on the property:

- 1. There has been recent development to the rear of the property
- 2. Two of the roof stormwater pipes are discharging onto the property
- 3. There is a pit of some description also discharging onto the property

As there are several issues I will address them one at a time.

1. There has been recent development to the rear of the property

The development to the rear of your property was approved by Council with the condition of a drainage easement taken over all the rear properties. The condition of the easement means there can be no permanent construction on or over that portion of land. Additionally it gives Council certain rights of entry to maintain and or reconstruct if required. At this stage there is no evidence that the levels of the drain are incorrect or require adjusting. It was noted that some of the properties have constructed fences and these may be impeding the flow of water through the easement. As these do not constitute permanent works it is not within Councils authority to instruct or direct property owners to remove them. This is a civil matter between property owners.

2. Two of the roof stormwater pipes are discharging onto the property

It was noted that the front down pipe and one of the rear property down pipes are discharging on to the property. This is exacerbating the issue of water ponding on the property and causing the water to build up quickly. If you are unsure you want to direct the water to the property to the rear an attempt to connect the pipes to the kerb with properly connected one-way valves and downpipes may assist the water to be removed from the property. As this is part of the internal drainage it is recommended that you liaise with a qualified plumber as these works are the property owner's responsibility.

3. There is a pit of some description also discharging onto the property

From conversations on site it would appear that one of the roofs down pipes has historically being directed into a grey water tank system which has been decommissioned. This was observed by clear water being discharged from beneath the ground. This water is coming to the surface in the same location as the other water which will also add to any water collecting in the rear of the property. To rectify this you should liaise with a qualified plumber as these works are the property owner's responsibility.

Should you have any further enquiries, please do not hesitate to contact Council's Mr through Customer Service on 1 300 79 49 29.

Yours faithfully

INFRASTRUCTURE ENGINEER
INFRASTRUCTURE & ENVIRONMENT
FRASER COAST REGIONAL COUNCIL

Contact Officer:

Reference: Docs # 2011211

























