

AUCHENFLOWER FLOOD IMAGES

October 2010 – Image of dwelling following renovation ([redacted] Frontage)



October 2010 – Image of dwelling following renovation ([redacted] Frontage)



JM

QFCI Date: 20/09/11
Exhibit Number: 562

Tuesday 11 January 2011 3:45pm – Flooding in [REDACTED] Street



Tuesday 11 January 2011 10:48pm – Flooding in stairwell through wall



Thursday 13 January 2011 8:13am – Image of front of house ([REDACTED] Road)



Thursday 13 January 2011 8:07am – Image of rear of house ([REDACTED] Street)



Thursday 13 January 2011 7:40am – Image of [REDACTED] Street from deck



Thursday 13 January 2011 8:14am – Side of house (Flood line evident)



Thursday 13 January 2011 8:14am – Front of house; flood line evident



Thursday 13 January 2011 7:40am – Water still on deck



Thursday 13 January 2011 8:50am – Water receded off deck



Thursday 13 January 2011 9:09am – Image from rear deck to main



Thursday 13 January 2011 9:01am – bathroom and cabinetry damage



Thursday 13 January 2011 7:46am – kitchen and dining



Thursday 13 January 20119:06am – Image of house fronting [REDACTED] across from ours (houses unraised)



Thursday 13 January 20118:09am – Image of [REDACTED] Street (Houses unraised)

